

## UST Inspection Report

### Little Bighorn Camp

**Date of Report:** August 12, 2025

**Inspection Date & Time:** July 23, 2025, at 2:10 p.m. Mountain Daylight Time (MDT)

**Weather:** Sunny, ~85 degrees Fahrenheit

**Facility Owner:** Deceased

**Facility Owner Address:** N/A

**Facility Address:** I90 Frontage Rd. and Hwy 212

**Facility Representative:** None

**EPA Facility ID Number:** 2020044

**Reason for Inspection:** Routine compliance inspection

**Inspection Team:** Marta Grabowski, Inspector, EPA UST Program  
Roberta Person, Inspector, EPA UST Program

### UST System Description

The Little Bighorn Camp (Facility) is an abandoned facility located on the Crow Reservation in Crow Agency, Montana. The UST system has been out of use since approximately 2012. The Environmental Protection Agency's Facility records indicate the Facility has two, jacketed steel underground storage tanks (USTs) that were installed in January 1999. Tank 1 has an 8,000-gallon capacity and Tank 2 has a 12,000-gallon capacity. Piping is safe suction, single-walled fiberglass reinforced plastic (FRP).

### Inspection Narrative

On July 23, 2025, the EPA UST program personnel conducted an inspection at Little Bighorn Camp in Crow Agency, Montana. The EPA last inspected the Facility on October 14, 2022, and they selected it for routine re-inspection. Ms. Grabowski, the EPA inspector, did not attempt to contact a Facility representative, as the listed property owner is deceased. A responsible party (RP) search conducted by EPA in January 2025 concluded that there are no viable owners/operators for the USTs and the Facility is abandoned.

The EPA inspection team arrived at the Facility at 2:10 p.m. MDT and conducted a physical inspection of the UST system. Photographs of UST system components taken during the inspection are in Attachment A, and the inspection checklist is Attachment B.

### **Physical Observations**

The EPA inspector viewed the spill buckets/fill pipes, ATG risers, vents, and former dispensers. Fill pipes were locked and both spill buckets contained debris. One of the tank vents was significantly damaged. There was no recent paperwork or test records for the USTs.

### **Inspection Report Attachments**

- A. Photo log
- B. Inspection checklist

### **Signature**

Lead Inspector

**MARTA GRABOWSKI** Digitally signed by MARTA GRABOWSKI  
Date: 2025.08.12 10:30:42 -06'00'

---

Marta Grabowski

Date of signature