

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Jeanne Eckhart	Inspection Date	05/23/2023	Time	15:45
Inspection Due	2020-06-05T00:00:00Z	Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS3927000		
		API Well No			
		Lease Name	NRU		
		Well ID	5		
Location	NW 09 24N 07E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.705085	Longitude	-96.641119		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	02/23/2016	Last Test Result	Acceptable
Casing	4.5	Tubing	2.875	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 729
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	A fluid level was taken with a properly calibrated EPA Echometer. The fluid level taken during the inspection was 683 feet deep. This well was not connected during the inspection. The casing size was approximately 4.5". Two photographs were taken during this inspection and can be seen in the Inspection Photo Log.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.705085, -96.641119		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010168.JPG

Orientation: E

Date of Photo: 05/23/2023

Time of Photo: 3:55 PM

Latitude: 36.705085

Longitude: -96.641119

Photographer: Jeanne Eckhart

Description: This was the injection well OS3927000 at the time of the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.705085, -96.641119		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010169.JPG

Orientation: SE

Date of Photo: 05/23/2023

Time of Photo: 4:03 PM

Latitude: 36.705085

Longitude: -96.641119

Photographer: Jeanne Eckhart

Description: This was the injection well OS3927000 at the time of the inspection. The well was disconnected at the time of the inspection.