

MATERIAL HANDLING SYSTEM

1. Dust Explosions.

PREVENTATIVE MEASURES:

- a. Combustible gas detectors in all hoppers and silos.
- b. Air purge on all hoppers and Silos.

2. Solvent Buildup in the check hoppers.

PREVENTATIVE MEASURES:

- a. Optional Nitrogen purge on check hoppers.
- b. Calculated solvent content based on process conditions.

10/08/92
MATERIAL_HANDLING_AREA.RC_TXT

DOW CONFIDENTIAL