

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	3/12/2024	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Edna Oil Company, LLC	
Facility Name:	Henry Corley Tank Battery	
Facility Physical Location:	Latitude: 33.38013, Longitude: -92.79035	
(city, state, zip code)	El Dorado, AR, 71730	
Mailing address:	451 North Washington	
(city, state, zip code)	El Dorado, Arkansas, 71730	
County/Parish:	Union County	
Facility Phone Number	870-862-8237	
Facility Contact:	Tim Corley	
	dlatimer@ecgcpa.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002225	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Michael Blaha	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Uma Lad	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Kerri McCabe	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Glen Owens	AOGC	AOGC Inspector
EPA Lead Inspector Signature/Date		
	Michael Blaha	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Michael Blaha, Uma Lad, and Kerri McCabe arrived at Edna Oil Company, LLC, Henry Corley Tank Battery, located off Highway 7 (33.38013, -92.79035) at 8:50 AM on 3/12/2024 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. Glen Owens with Arkansas Oil and Gas Commission (AOGC) was present during the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the Edna Oil Company, LLC, Henry Corley Tank Battery, which contained two (2) separators, two (2) tanks, and one (1) open top tank.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, oil separators, pipes, and tanks located at the facility, see Appendix 1 (photo log), photo No. 1. For additional GPS location and photo metadata, see Appendix 1.

I observed the missing catchment buckets under the loading pipes outside of secondary containment, see photo No. 2.

I observed loose oil outside of secondary containment near the open top tank as well as loose oil inside secondary containment, see photo No. 3, photo No. 4, and photo No. 6.

I observed the secondary discharge valve without a cap with standing water below the valve, see photo No. 5.

Outside of secondary containment, I observed a separator and a tank disconnected and clean without proper out of service markings, see photo No. 7.

I observed a Total Dissolved Solids (TDS) reading of 33,425 mg/L outside of secondary containment in a low spot behind (NE) the facility, see photo No. 8 and photo No. 9.

I observed a TDS reading of 350.6 mg/L in the tributary behind (NE) the facility, see photo No. 10 and photo No. 11.

All TDS field readings observed throughout the inspection were taken with a properly calibrated, EPA issued, YSI pro 30 conductivity meter.

Section III – AREAS OF CONCERN

No closing conference was held due to no Edna Oil Company, LLC staff being present during the inspection. Areas of concern at the time of the inspection include the missing buckets for the loading lines outside of secondary containment, loose oil outside of secondary containment, loose oil within secondary containment, secondary discharge pipe not having a cap, and high TDS readings outside of secondary containment.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 11 photos taken 3/12/2024

Appendix 1

Photograph Log

11 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010166

Orientation: NE

Date of Photo: 3/12/2024

Time of Photo: 8:59 AM

Latitude: 33.368889

Longitude: -92.784483

Photographer: Michael Blaha

Description: This photo was taken looking NE showing an overview of the facility. This facility did not have a facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010167

Orientation: NW

Date of Photo: 3/12/2024

Time of Photo: 9:07 AM

Latitude: 33.368931

Longitude: -92.784481

Photographer: Michael Blaha

Description: This photo was taken looking NW at the facility showing the loading lines outside of secondary containment without catchment buckets.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010168

Orientation: SW

Date of Photo: 3/12/2024

Time of Photo: 9:09 AM

Latitude: 33.368903

Longitude: -92.784481

Photographer: Michael Blaha

Description: This photo was taken looking SW showing oil staining outside of secondary containment SE of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010169

Orientation: NW

Date of Photo: 3/12/2024

Time of Photo: 9:10 AM

Latitude: 33.368911

Longitude: -92.784481

Photographer: Michael Blaha

Description: This photo was taken looking NW showing the loose oil within secondary containment that contains one open top tank.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010170

Orientation: SW

Date of Photo: 3/12/2024

Time of Photo: 9:11 AM

Latitude: 33.368931

Longitude: -92.784497

Photographer: Michael Blaha

Description: This photo was taken looking SW showing the secondary containment discharge valve without a cap and standing water below the valve.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010171

Orientation: W

Date of Photo: 3/12/2024

Time of Photo: 9:12 AM

Latitude: 33.368933

Longitude: -92.784494

Photographer: Michael Blaha

Description: This photo was taken looking W showing loose oil and water inside secondary containment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 7

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010172

Orientation: NW

Date of Photo: 3/12/2024

Time of Photo: 9:18 AM

Latitude: 33.368939

Longitude: -92.784547

Photographer: Michael Blaha

Description: This photo was taken looking NW showing the clean and disconnected tanks outside of secondary without proper out of service markings.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 8

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010173

Orientation: NA

Date of Photo: 3/12/2024

Time of Photo: 9:30 AM

Latitude: 33.380477

Longitude: -92.790328

Photographer: Michael Blaha

Description: This photo was taken showing a Total Dissolved Solids (TDS) reading of 33,425 mg/L outside of secondary containment in a low spot behind (NE) the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 9

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010177

Orientation: NE

Date of Photo: 3/12/2024

Time of Photo: 9:33 AM

Latitude: 33.380477

Longitude: -92.790328

Photographer: Michael Blaha

Description: This photo was taken at the same location as photo No. 8 showing the low spot behind (NE) of the facility where the TDS reading was taken.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 10

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010179

Orientation: NA

Date of Photo: 3/12/2024

Time of Photo: 9:39 AM

Latitude: 33.380515

Longitude: -92.790122

Photographer: Michael Blaha

Description: This photo was taken showing a TDS reading of 350.6 mg/L in the tributary behind (NE) the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 11

Location: 33.8013, -92.79035		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: R0010182

Orientation: NE

Date of Photo: 3/12/2024

Time of Photo: 9:47 AM

Latitude: 33.380643

Longitude: -92.790347

Photographer: Michael Blaha

Description: This photo was taken at the same location as photo No. 10 showing the tributary (NE) of the facility where the TDS reading was taken.