

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	07/16/2024	Time	07:15
		Operator Representative	Bandwheel Production Company, LLC		
Operator Info	Bandwheel Production Company, LLC P.O. Box 700426 Tulsa, OK 74170 Phone: 918-932-8418	Inventory ID	OS3272000		
		API Well No			
		Lease Name	Bandwheel		
		Well ID	CI-14		
Location	NW 13 23N 08E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.474521	Longitude	-96.398796		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Bandwheel Production Company,		
Inspect No.		Date Last MIT	03/03/2023	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure Lease Status		Fittings	N	N	Max Pressure 404
		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Lester well service run in hole and tag the top of cement on the bottom plug at 800 feet below the surface, this plug was set and observed by EPA on 7/15/2024. From 800 feet, Lester well service circulated 70 sacks of cement to the surface. Inspector observed cement standing at the surface with no fall back.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.474521, -96.398796		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010489

Orientation: N/A

Date of Photo: 07/16/2024

Time of Photo: 9:37 AM

Latitude: 36.474521

Longitude: -96.398796

Photographer: Matthew Allen

Description: This was well OS3272000 standing full of cement at the end of plugging operations.