

ENGINEER:
INDUSTRIAL HYGIENE SURVEY DATA SHEET (See instructions on reverse side)
THE TRAVELERS INSURANCE COMPANIES
HARTFORD, CONNECTICUT 06183 (Location 2-5-116)

PAGE 2 OF 4

CUSTOMER GENUINE PARTS CO., INC. - RAYLOC		LOCATION 100 Rayloc Dr. Hancock, Maryland 21750	SURVEY DATE February 28, 1989
POLICY NUMBER/CLAIM NUMBER UB 168 T 3075		BUSINESS UNIT ☒ SAM/CAD ☐ CAM ☐ FIELD (AMG.) ☐ CLAIM ☐ CSSC ☐ OTHER (EXPLAIN)	

INSTRUMENTATION

INSTRUMENT HI FLOW SAMPLER		MANUFACTURER GILIAN	MODEL HFS-113
SERIAL NUMBER	TIC NUMBER	REASON FOR SAMPLING - INCLUDE PROCESS OR OPERATION DESCRIPTION & CONTROLS	
1017	3/81	Division management's request to assess employee's potential exposure to asbestos fibers in the	
1994	25/82	Brake Shoe Department during typical brake rebuild operations such as chopping, midas belt sorting,	
	68/83	clutch disc drilling, burning, and disc brake riveting. Remanufacturing of automotive parts.	
10459	181/85		
5879	101/84		

COLLECTION (SAMPLING) MEDIA MILIPORE FILTERS. (OPEN FACED)	ANALYSIS REQUIRED ASBESTOS FIBERS (Including TEMS Analysis)
---	--

SAMPLE DATA

TIC INST NO.	SAMPLE NUMBER MP	SAMPLING LOCATION (INCLUDE EMPLOYEE'S NAME)	COLLECTION TIME		COLLECTION DURATION (MINS)	FLOW RATE (LPM)	SAMPLER POSITION	NUMBER OF PERSONS IN AREA	EXPOSURE TIME (MINS)	SHIFT DURATION (MINS)	COMMENTS
			Start	End							
25/82	428F	Rick Vance	1240	1411	91	2.0	PS	8	480	540	General ventilation
		Midas Belt Sorter									
25/82	220F	Rick Vance	1411	1557	106	2.0	PS	8	480	510	General ventilation
		Midas Belt Sorter									
68/83	426F	Darrel Miller	0744	1147	243	2.0	PS	2	450	510	Local exhaust ventilation
		Clutch Disc Driller									
68/83	425F	Darrel Miller	1237	1408	91	2.0	PS	2	450	510	Local exhaust ventilation
		Clutch Disc Driller									

OFFICE Baltimore	ENGINEER J. E. David, III	SIGNATURE <i>Joseph E. David, III</i>	DATE SIGNED 5-19-89
---------------------	------------------------------	--	------------------------

NOVO20297