

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	06/27/2024	
Media Program:	Water, Clean Water Act (Brine)	
Regulatory Program(s)	Brine (NPDES)	
Company Name:	CapturePoint, LLC	
Facility Name:	North Burbank Unit (NBU) 57 Battery	
Facility Physical Location:	36.784534, -96.739868	
(city, state, zip code)	Webb City, Oklahoma, 74652	
Mailing address:	1833 S. Morgan Road	
(city, state, zip code)	Oklahoma City, Oklahoma, 73128	
County/Parish:	Osage	
Facility Phone Number	918-287-6811	
Facility Contact:	Talia Clark	HSE Tech
FRS Number:	n/a	
Identification/Permit Number:	OKU002083	
Media Identifier Number:	n/a	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Matthew Allen	EPA/Region 6 ECDW	Inspector
Talia Clark	CapturePoint, LLC	HSE Tech
EPA Lead Inspector Signature/Date		
	Matthew Allen	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector Matthew Allen arrived at the CapturePoint, LLC / North Burbank Unit (NBU) 57 Battery (EPA ID No. OKU002083) at 1:40 PM on 06/27/2024 for an announced inspection. This was an EPA inspection in response to a National Response Center Spill Report (NRC No. 1402710) which was received by EPA Region 6. The spill occurred on 06/23/2024. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. CapturePoint, LLC representative, Talia Clark participated during the inspection. There was no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection at the CapturePoint, LLC North Burbank Unit 57 Battery, where an equipment failure resulted in the release of a company estimated 4 barrels of oil and 800 barrels produced water. The released fluids migrated southwest into an unnamed tributary of Mud Creek.

Section II – OBSERVATIONS

Inspector observed the release point GPS: 36.784529, -96.739874 and the point of entry into an unnamed tributary of Mud Creek GPS: 36.784390, -96.740414. At the time of the inspection, the operator had removed all contaminated water from the flowpath and the impacted tributary near the point of entry (POE).

I observed a temporary containment dam used in cleanup and flushing operations at GPS: 36.782229, -96.741974. At the time of the inspection, the impacted waters had been removed from the impacted tributary at this location.

I observed the end of spill impacts and the lowermost temporary containment dam at GPS: 36.780665, -96.747074. At the time of the inspection there was no water present in the impacted tributary at this location.

There are no photos available for this inspection.

Section III – AREAS OF CONCERN

The primary areas of concern included the impacted soil and vegetation across the overland flowpath, and the residual brine located along the main channel of the impacted, unnamed tributary of Mud Creek.

Section IV – FOLLOW UP

Inspector will follow up via phone calls and site visits as needed until the impacted area is cleaned to “pre-spill” condition.

Section V – LIST OF APPENDICES

There are no appendices to this report.