

HFC Import Inspection Worksheet

This worksheet is for inspection of Imported Hydrofluorocarbons (HFCs) subject to 40 CFR Part 84			
Insp. No: 20231206-0810		Inspector(s): ☐ E. Felix ☐ N. Dancher ☒ A. Isin ☐ J. Iatropulos	
Insp. Date: 12/6/2023		Start Time/Stop Time: Start 8:03am, End 9:00am	
Location of Inspection			
Facility Name: Price 3		Facility Type: Customs and Border Protection (CBP) Warehouse	
Address: 1119 E 230th St, Carson, CA 90745		CBP POC Contact Information: Kent Koike, 310-971-2700	
☒ Indicate here if entry was not filed at time of inspection Importer Information (from Entry Documents) ☒ Indicate here if consignee is the same as importer			
Importer Name: Mexichem Fluor Inc.		Consignee Name:	
Importer Address: 4990B ICI Road, PO Box 30, St. Gabriel, LA 70776		Consignee Address:	
Importer No : 27-178566700		POC Contact Information: sean.cunningham@mexichem.com	
Visual Inspection HFC #1			
Product Description: HFC-134A		Shipment/ Entry No: 916-5041625-7	
Chemical name/formula: 1,1,1,2-Tetrafluoroethane		Shipping Container No: INFL1001123	
Container Type: ☐ Service Can ☐ Ton Tank ☒ ISO Tank		Arrival Date: 11/27/2023	
☐ Refillable Cylinder ☐ Disposable Cylinder		Listed Qty: 1	Listed Mass: see below Actual Mass: N/A ☐ lb ☒ kg ☐ ton
On tank: Max Gross: 36,000 kg, Tare: 6,340 kg, Capacity: 21,500 Liters Entry summary form and invoice list 17,880 kg.			
Visual Inspection HFC #2			
Product Description:		Shipment/ Entry No:	
Chemical name/formula:		Shipping Container No:	
Container Type: ☐ Service Can ☐ Ton Tank ☐ ISO Tank		Arrival Date:	
☐ Refillable Cylinder ☐ Disposable Cylinder		Listed Qty:	Listed Mass: Actual Mass: ☐ lb ☐ kg ☐ ton
Visual Inspection Notes:			
Visual Inspection HFC #3			
Product Description:		Shipment/ Entry No:	
Chemical name/formula:		Shipping Container No:	
Container Type: ☐ Service Can ☐ Ton Tank ☐ ISO Tank		Arrival Date:	
☐ Refillable Cylinder ☐ Disposable Cylinder		Listed Qty:	Listed Mass: Actual Mass: ☐ lb ☐ kg ☐ ton
Visual Inspection Notes:			
Inspection Summary			
Evidence/Samples taken and Description: None			
Potential Follow-Up/Areas of Concern (e.g. potential deficiencies, actions taken by facility (if applicable)): N/A			
Inspection photo numbers: PC060001.jpg-PC060022.jpg			
Camera Information: ☐ Nikon Coolpix WD300 ☒ Sony Olympos		Other: Photographer: ☐ E. Felix ☐ N. Dancher ☒ A. Isin ☐ J. Iatropulos	
Lead Inspector Signature: AMELIE ISIN		Supervisor Signature: MARK PALERMO	
Digitally signed by AMELIE ISIN Date: 2023.12.22 13:39:36 -05'00'		Digitally signed by MARK PALERMO Date: 2024.01.01 09:46:53 -05'00'	
Guidance for Inspectors:			
Inspector should obtain copies of the following when conducting inspections for CBP:			
• Entry documents • Invoice/Packing lists • Bill of lading			
Inspector should obtain the following key photographs:			
• All sides of container to include any labels.			