

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/10/2024	Time	09:30	
		Operator Representative Park WM				
Operator Info	Park WM	Inventory ID OS2455000				
	P.O. Box 718	API Well No				
	Skiatook, OK 74070	Lease Name TBD				
	Phone: 918-288-7752	Well ID WF21				
Location	NE 22 20N 12E	Status	Inactive	Well Type	Enhanced Recovery	
Latitude	36.197932	Longitude	-96.010738			
Inspection Reason	Plugging Witnessed	Responsible Company at		Park WM		
		Time of Inspection				
Inspect No.		Date Last MIT		Last Test Result		
Casing	4.5	Tubing		USDW		
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	N	Tubings	Annulus	AUTHORIZED		
		Fittings	N	N	Max Pressure	371
		Actual Pressure			Max Volume	
		Determined?			Max Inj Units	Barrels Per Month
		Static Fluid Level				
		Determined?				
		Injection Rate (bpd)				
Inspection Comments		EPA inspector observed Lester Well Service run 1385 feet of tubing into well OS2455000 and circulate 120 sacks of class A cement to the surface. Inspector observed the well standing full of cement with no fallback. Well successfully plugged. BIA inspector Ira Lookout and Osage Nation DNR inspector Stephen Wynn were also present during the inspection.				
Inspector Signature						
Supervisor Signature						

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.197932, -96.010738		
City: Tulsa	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010519

Orientation: E

Date of Photo: 10/10/2024

Time of Photo: 9:55 AM

Latitude: 36.197932

Longitude: -96.010738

Photographer: Matthew Allen

Description: This was well OS2455000 with cement circulating to the surface.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.197932, -96.010738		
City: Tulsa	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010522

Orientation: E

Date of Photo: 10/10/2024

Time of Photo: 10:56 AM

Latitude: 36.197932

Longitude: -96.010738

Photographer: Matthew Allen

Description: This was well OS2455000 standing full of cement with no fallback.