

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/13/2026	Time	14:05
		Operator Representative	Performance Energy Resources, LLC		
Operator Info	Performance Energy Resources, LLC	Inventory ID	OS4742000		
	P.O. Box 628	API Well No			
	Barnsdall, OK 74002	Lease Name	Anticline		
	Phone: 918-847-2531	Well ID	2E		
Location	NW 12 24N 11E	Status	Inactive	Well Type	Disposal
Latitude	36.575424	Longitude	-96.080446		
Inspection Reason	Responsible Company at		Performance Energy Resources		
	Time of Inspection				
Inspect No.		Date Last MIT	03/12/1987	Last Test Result	Fail
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 473
FLM Canister Pressure		Actual Pressure			Max Volume 725
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed well, OS4742000 (Anticline 2E). At the time of the inspection the well was equipped with open ended tubing which was blocked with mud/grass/debris which prevented the observance of the the fluid level down the tubing. The annulus was open to the atmosphere and the fluid level was observed to be 877 feet below the annular opening. The well was disconnected, there was no well sign present and the well appeared to be temporarily abandoned. At the time of the inspection the well was overdue for MIT.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2026.02.26 15:09:03 -06'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2026.02.27 07:16:14 -06'00'				

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.575424, -96.080446		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010771

Orientation: SSW

Date of Photo: 03/07/2026

Time of Photo: 3:07PM

Latitude: 36.575424

Longitude: -96.080446

Photographer: Matthew Allen

Description: This was well OS4742000 at the time of the inspection. At the time of the inspection the well was overdue for MIT. There was no well sign present at the location. The tubing was obstructed with grass and dirt preventing observance of the fluid level down the tubing. The annulus fluid level was observed to be 877' below the surface.