

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	11/20/2025	Time	12:50
		Operator Representative	Performance Petroleum Co		
Operator Info	Performance Petroleum Co P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS6161000		
		API Well No			
		Lease Name	Ballew		
		Well ID	05-1		
Location	SW 35 26N 11E	Status	Inactive	Well Type	Disposal
Latitude	36.683551	Longitude	-96.091284		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Performance Petroleum Co		
Inspect No.		Date Last MIT	06/02/2008	Last Test Result	Acceptable
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 300
FLM Canister Pressure		Actual Pressure			Max Volume 36000
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspection conducted as follow-up to previous inspection where wellhead configuration indicated possible continued use of the well for injection/disposal. At the time of the inspection, the well was converted to gas production, but TA'd which was verified by Jim Virden with Performance Petroleum Co. At the time of the inspection, the well was 2.375 tubing terminated by a cutoff valve at the surface. Inspector verified on a previous site visit, and again during the inspection, the poly flowline was not connected to the injection pump at the tank battery. After consultation with company representatives and multiple site visits, there were no areas of concern.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.683715, -96.08638		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010768

Orientation: ENE

Date of Photo: 11/20/2025

Time of Photo: 1:53PM

Latitude: 36.683715

Longitude: -96.08638

Photographer: Matthew Allen

Description: This was well OS6161000. At the time of the inspection, the well was reduced to a 2" ball valve atop the tubing. The flowline was disconnected. The flowline was also disconnected at the tank battery. Jim Virden stated the well was previously converted to gas production.