

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	11/06/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Milam Oil Corporation	
Facility Name:	MacCullar Lease	
Facility Physical Location:	33.266085, -92.508158	
(city, state, zip code)	Old Union, Arkansas 71730	
Mailing address:	1605 Haynesville Hwy.	
(city, state, zip code)	El Dorado, Arkansas 71730	
County/Parish:	Union County	
Facility Phone Number	870-862-4258	
Facility Contact:	John Milam	
	jmilam@milamconst.com	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		12 DEC 2019
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Milam Oil Corporation oil and gas facility located at latitude 33.256008 and longitude -92.523928 near Old Union, Arkansas on 11/06/2019 for an unannounced inspection. There were no representatives of Milam Oil Corporation present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is located on the MacCullar Lease (Crain City).

Section II - OBSERVATIONS

I observed fluids in the secondary containment pit at the tank battery, which was full at the time of the inspection. I observed that there was about 6 inches of freeboard on the pit before the fluids would overflow. The secondary containment pit was leaking out of the southwest corner of the berms. I observed some surface damage south of the bermed area and facility due to brine leaking from the facility. With a calibrated YSI Pro 30 conductivity meter, I took a Total Dissolved Solids (TDS) reading from inside the secondary containment pit and it measured 1,200 milligrams per liter (mg/L).

Section III – AREAS OF CONCERN

The secondary containment pit was inadequate, full, and allowed fluids to leak from the facility.

Section IV – FOLLOW UP

EPA water enforcement will conduct a follow up inspection in approximately 6 months.

Section V – LIST OF APPENDICES

N/A