

U.S. DEPARTMENT OF LABOR
OCCUPATIONAL SAFETY & HEALTH ADMINISTRATION
ROOM 208, FEDERAL BUILDING
211 W. FERGUSON STREET

(214) 595-2438

Tyler, Texas 75701

May 4, 1978




Mr. Charles Kuenemann
Safety and Security Manager
Tyler Pipe Industries, Inc.
Tyler, Texas 75701

Dear Mr. Kuenemann:

Re: letter of April 28, 1978, in which you requested information on the September 1977 monitoring inspection and December 1977 complaint inspection of Tyler Pipe.

Information requested is shown on the enclosed sheets.

Sincerely,


ROBERT B. SIMMONS
Area Director

2 Enclosures

MONITORING INSPECTION: SEPTEMBER 1977

<u>Area</u>	<u>Item</u>	<u>Amount</u>	<u>Over PEL</u>
Pallet Muller South	Silica	0.147 mg/m ³	NO
Paller Muller South	Silica	0.60 mg/m ³	NO
Area Sample PM wheel	Silica	1.54 mg/m ³	YES
456 line slinger	Silica	1.48 mg/m ³	YES
Area 456 line slinger	Silica	1.36 mg/m ³	YES
Area 234 line slinger	Silica	0.16 mg/m ³	NO
234 line slinger	Silica	1.29 mg/m ³	NO
PM wheel	Silica	0.61 mg/m ³	NO

COMPLAINT INSPECTION: DECEMBER 1977- FEBRUARY 1978

<u>Area</u>	<u>Item</u>	<u>Amount</u>	<u>Over PEL</u>
Hub Core #1	Silica	2.22 mg/m ³	Yes
Hub Core #2	Silica	1.35 mg/m ³	No
Muller North Plant	Silica	2.83 mg/m ³	Yes
Hub Core #7 & 8	Silica	1.36 mg/m ³	Yes
Core #3 & 4	Silica	1.59 mg/m ³	Yes
Core #1 & 2	Silica	1.46 mg/m ³	Yes
Set Core Wheel 3	Silica	1.69 mg/m ³	Yes
Core Relief	NH ⁴	9.1 mg/m ³	No
Hub Core #2	NH ⁴	8.0 mg/m ³	No
Core Relief	Phenol	3.0 mg/m ³	No
Hub Core #10	Phenol	1.4 mg/m ³	No
Hub Core #5 & 6	Silica	Ø	No