



PROJECT NO. 14

ExposureType: 45 deg. S.Place: Sayville, L. I.
Cleveland, Ohio
Joplin, Mo.
San Francisco, Cal.
New Orleans, La.Date: September, 1948Exposure SpecimensFlat - 12" x 18", 20 gaugeAngle - 4" x 4" x 12", 3/8" thick.Specimen LayoutsFLAT SPECIMEN

Left 9 inches and entire back,
1 primer coat.
Right 9 inches, 2 primer coats.
Upper 6 inches, 1 finish coat.
Lower 6 inches, primer exposed.

ANGLE SPECIMEN

Lower 6 inches and entire
back, 1 primer coat;
Upper 6 inches, 2 primer coats.
Middle 6 inches, 1 finish coat.
Upper and lower three inches,
primer exposed.

N2791.01

L.I.A. PROJECT NO. 14

FLAT SPECIMENS

SAYVILLE, N. Y.

Inspected by: L. L. Carrick, O. F. Shobe
 Date Exposed: 9/1/48
 Date Inspected: 6/4/56

L.I.A. PANEL NO.	GENERAL CORRO- SION RATING Primer Areas		L.I.A. PANEL NO.	GENERAL CORRO- SION RATING Primer Areas		L.I.A. PANEL NO.	GENERAL CORRO- SION RATING Primer Areas	
	1	2		1	2		1	2
203A & B*	4	4	223A & B	8	10	243A & B	0	4
204A & B	0	6	224A & B	8	10	244A & B	4	10
205A & B	5	5	225A & B	10	10	245A & B	5	10
206A & B	4	9	226A & B	10	10	246A & B	10	10
207A & B	0	6	227A & B	10	10	247A & B	1	10
208A & B	0	5	228A & B	5	10	248A & B	0	7
209A & B	7	9	229A & B	10	10	249A & B	10	10
210A & B	7	8	230A & B	9	10	250A & B	9	10
211A & B	7	7	231A & B	10	10	251A & B	10	10
212A & B	7	8	232A & B	8	9	252A & B	10	10
213A & B	6	8	233A & B	0	10	253A & B	2	10
214A & B	9	9	234A & B	10	10	254A & B	7	10
215A & B	9	9	235A & B	6	10	255A & B	10	10
216A & B	10	10	236A & B	6	10	256A & B	10	10
217A & B	10	10	237A & B	9	10	257A & B	9-	10
218A & B	9	10	238A & B	0	2	258A & B	9*	10
219A & B	8	10	239A & B	8	10	259A & B	8	10
220A & B	10	10	240A & B	3	10	260A & B	10	10
221A & B	10	10	241A & B	9	10	261A & B	7	10
222A & B	9	10	242A & B	1	9	262A & B	0	1

* Ratings in areas 1 and 2 are the average ratings for panels A & B for these areas

Inspected by: L. L. Carrick, G. F. Shobe
 Date Exposed: 9/1/48
 Date Inspected: 6/4/56

Page 2
 Flat Specimens

L.I.A. PANEL NO.	GENERAL CORRO- SION RATING Primer Areas		L.I.A. PANEL No.	GENERAL CORRO- SION RATING Primer Areas	
	1	2		1	2
263A & B	1	8	312A & B	8+	10
264A & B	6	10	313A & B	18	10
265A & B	10	10	314A & B	10	10
266A & B	0	2	315A & B	10	10
267A & B	4	9	331A & B	0	2
268A & B	0	0	341A & B	10	10
266A & B	0	3	341A & B	8+	10
287A & B	6	10	342A & B	9	10
288A & B	0	10			
289A & B	8	10			
290A & B	7	10			
291A & B	0	4			
292A & B	8	10			
293A & B	2	10			
294A & B	9	10			
295A & B	8	10			
297A & B	0	3			
299A & B	0	2			
301A & B	0	1			
302A & B	8	9			
307A & B	3	9			
310A & B	0	0			
311A & B	5	10			

* Ratings in areas 1 and 2 are the average ratings for panels A & B for these areas.

L.I.A. PROJECT NO. 14

ARTILE SPECIMENS

SAITVILLE, N. Y.

Inspected by: L. L. Carrick, O. F. Shobe
 Date Exposed: 9/1/48
 Date Inspected: 6/4/56

L.I.A. PANEL NO.	GENERAL CORRO- SION RATING Primer Areas		L.I.A. PANEL NO.	GENERAL CORRO- SION RATING Primer Areas		L.I.A. PANEL NO.	GENERAL CORRO- SION RATING Primer Areas	
	1	2		1	2		1	2
201A & B*	0	6	221A & B	4	9	241A & B	1	6
202A & B	2	10	222A & B	5	9	242A & B	6	10
205A & B	0	9	225A & B	7	9	245A & B	5	9
206A & B	1	9	226A & B	6	9	246A & B	8	9
207A & B	1	8	227A & B	7	8+	247A & B	4	10
208A & B	1	8	228A & B	4	8	248A & B	3	8
209A & B	4	10	229A & B	5	9	249A & B	8	10
210A & B	7	10	230A & B	7	9	250A & B	7	9
211A & B	8	9	231A & B	7	9	251A & B	8	10
212A & B	5	8	232A & B	7	9	252A & B	8+	9
213A & B	1	8	233A & B	2	9	253A & B	2	9
214A & B	5	7	234A & B	7	9	254A & B	3	9
215A & B	6	8	235A & B	7	9	255A & B	7+	10
216A & B	7	9	236A & B	6	9	256A & B	7	9
217A & B	6	9	237A & B	4	9	257A & B	2	9
218A & B	8	10	238A & B	5	9	258A & B	6	8+
219A & B	7	9	239A & B	4	9	259A & B	7	8+
220A & B	9	10-	240A & B	5	9	260A & B	7	9
221A & B	8	9	241A & B	7	9	261A & B	2	8+
222A & B	7+	9	242A & B	2	8	262A & B	0	5

* Ratings in areas 1 and 2 are the average ratings for panels A & B for these areas.

Inspected by: L. L. Carrick, O. P. Shobe
 Date Exposed: 9/1/48
 Date Inspected: 6/1/56

Page 2
 Angle Specimens

L.I.... PANEL NO.	GENERAL CORRO- SION RATING	
	Primer Areas	
	1	2
263A & B*	1	6
264A & B	6	10
265A & B	7	10
266A & B	0	2
267A & B	1	8
268A & B	0	3
269A & B	0	6
287A & B	4	8
288A & B	4	9
289A & B	8	9
290A & B	2	8
291A & B	1	5
292A & B	6	8
293A & B	3	9
294A & B	9	10
295A & B	7	10
297A & B	0	2
299A & B	0	2
301A & B	0	1
302A & B	5	9
307A & B	2	6
310A & B	0	0
311A & B	4	7

L.I.... PANEL NO.	GENERAL CORRO- SION RATING	
	Primer Areas	
	1	2
312A & B	5	10
313A & B	5	8
314A & B	5*	8
315A & B	6	8
316A & B	0	4
317A & B	7	8*
318A & B	5	7
319A & B	4	7*

* Ratings in areas 1 and 2 are the average ratings for panels A & B for these areas.