



A & E Metal Recycling And Packaging, Inc.
EPA Clean Water Act Inspection
Photo Album
11-18-21

Inspectors Alex Rosenberg and
Rachel Olugbemi



A&E Metal
449 American

EPA – MSGP Inspection
11/18/21



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 3

Open Dumpsters;
Possible Outfall 5



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 – CATCHMENT TO POSSIBLE OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 – CATCHMENT TO POSSIBLE OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2 & 1



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 1



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 1



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

Possible Outfall 1 -
behind stockpiles in
south of property



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



Possible Outfall 2

A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 – CATCHMENT TO POSSIBLE OUTFALL 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3

Possible Outfall 3 –
from overflow
culvert of wetland
pond



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 1 –
CATCHMENT
TO POSSIBLE
OUTFALL 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 2

Possible Outfall 4 –
from Area 2




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 2




A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 2



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21

AREA 3



A&E Metal
449 American Legion HWY, Westport MA
EPA – MSGP Inspection
11/18/21