

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	06/02/2025	Time	12:15
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS0508000			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name North Burbank Unit			
	Allen, TX 75013	Well ID 82-W6			
	Phone: 832-300-8221				
Location	SW 35 27N 05E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.774004	Longitude	-96.737961		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection		CapturePoint, LLC	
Inspect No.		Date Last MIT			
Casing	5.5	Tubing	2.375	Last Test Result	USDW
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 801
FLM Canister Pressure		Actual Pressure		Max Volume	
Lease Status	Active	Determined?		Max Inj Units	Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments		Inspector observed the well location after surface restoration was completed. There were no areas of concern at the time of the inspection.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.774004, -96.737961		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010686

Orientation: S

Date of Photo: 6/2/2025

Time of Photo: 12:16 PM

Latitude: 36.774004

Longitude: -96.737961

Photographer: Matthew Allen

Description: This was the location of well OS0508000 after surface restoration was completed.