

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	09/03/2025	Time	10:00
		Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS2898000		
		API Well No			
		Lease Name	NAVAL RESERVE UNIT		
		Well ID	30W3		
Location	NW 34 24N 07E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.520794	Longitude	-96.547271		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	06/25/2019	Last Test Result	Fail
Casing	5.5	Tubing	2.88	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 721
Lease Status	Active	Actual Pressure			Max Volume
Barrel Monitor Hooked Up?	N	Determined?			Max Inj Units Barrels Per Month
Barrel Fluid Level (%)		Static Fluid Level			
Flowline Hooked Up?	N	Determined?			
Injecting	N	Injection Rate (bpd)			
Inspection Comments	Well, OS2898000 was wireline perforated every 50 feet beginning at 500 feet below surface with the final perforation being at 50 feet below the surface. Orr Energy Services ran in well to 600 feet below surface and pumped 25 sacks of class A cement to surface then pulled the working string from the well. Orr connected to the 2 7/8-inch tubing which was already cemented inside the 5 1/2-inch casing and squeezed 25 sacks of class A cement until the well reached 1500psi. The well fell back to 1000psi and valves were closed locking 1000psi of cement pressure on the 2 7/8-inch tubing. Plugging activities were completed in accordance with the EPA approved plugging plan.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.520794, -96.547271		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_0190

Orientation: N/A

Date of Photo: 09/03/2025

Time of Photo: 12:55 PM

Latitude: 36.520794

Longitude: -96.547271

Photographer: Matthew Allen

Description: This was well OS2898000 at the time of the inspection with cement circulated to the surface.