



Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	03/12/2024	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Jerry Langley Oil Company, LLC	
Facility Name:	T.D. Murphy SWD Tank and T.D. Murphy Tank Battery	
Facility Physical Location:	Latitude: 33.34011, Longitude: -92.68934	
(city, state, zip code)	Smackover, AR, 71724	
Mailing address:	100 East 7 th Street	
(city, state, zip code)	Smackover, AR 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-3042	
Facility Contact:	Jerry C. Langley jloc58@yahoo.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002235	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Kerri McCabe	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Michael Blaha	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Michael Blaha, Kerri McCabe, and I, Uma Lad, arrived at Jerry Langley Oil Company, LLC, T.D. Murphy SWD Tank and Jerry Langley Oil Company, LLC, T.D. Murphy SWD Tank and T.D. Murphy Tank Battery, located off a lease road near All Gulf Road (33.34011, -92.68934) at 4:30 PM on March 12, 2024, for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection at the Jerry Langley Oil Company, LLC, T.D. Murphy SWD, which consists of three storage tanks, and at the Jerry Langley Oil Company LLC, T.D. Murphy Tank Battery, which consists of two storage tanks.

Section II - OBSERVATIONS

2.1. T.D. Murphy SWD Tank

I observed the facility sign, secondary containment, pipes, valves, and tanks located at the facility; see Appendix 1 (photo log), photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

I observed a tank with a leaking valve, see photo No. 3.

I observed an uncapped secondary containment drainage pipe containing a flowline, see photo No. 4. Outside of secondary containment, I observed standing water with an oil sheen, see photo No. 5.

2.2. T.D. Murphy Tank Battery

I observed the facility sign, secondary containment, pipes, valves, and tanks located at the facility, see photo No. 6.

I observed an uncapped secondary containment pipe containing a flowline that was surrounded by oil-stained soil, see photo No. 7. I observed oil-stained soil around a transfer valve with no catchment, see photo No. 8.

Jerry Langley Oil Company, LLC -T.D. Murphy SWD Tank and T.D. Murphy Tank Battery / ARU002235 (CWA)
Inspection Date 03/12/2024

Section III – AREAS OF CONCERN

No closing conference was held due to no Jerry Langley Oil Company, LLC staff being present during the inspection.

Areas of concern at the time of the inspection at T.D. Murphy SWD Tank include the leaking valve at the storage tank, missing cap for the secondary containment drainage pipe, and the oil sheen in standing water outside of secondary containment.

Areas of concern at the time of the inspection at T.D. Murphy Tank Battery include the missing cap for the secondary containment drainage valve, loose oil around the secondary containment drainage pipe outside secondary containment, loose oil surrounding the transfer pipe outside secondary containment, and missing catchment bucket at the transfer valve.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 8 photos taken on 03/12/2024

Jerry Langley Oil Company, LLC - T.D. Murphy SWD Tank and T.D. Murphy Tank Battery / ARU002235 (CWA)
Inspection Date 03/12/2024

Appendix 1

Photograph Log

8 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010227**Orientation:** NE**Date of Photo:** 03/12/2024**Time of Photo:** 4:34 PM**Latitude:** 33.34011**Longitude:** -92.68934**Photographer:** Uma Lad**Description:** This photo was taken looking northeast and shows the facility sign at T.D. Murphy SWD Tank.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010228**Orientation:** N**Date of Photo:** 03/12/2024**Time of Photo:** 4:35 PM**Latitude:** 33.33999**Longitude:** -92.68930**Photographer:** Uma Lad**Description:** This photo was taken looking north and shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010231**Orientation:** S**Date of Photo:** 03/12/2024**Time of Photo:** 4:38 PM**Latitude:** 33.34026**Longitude:** -92.68941**Photographer:** Uma Lad**Description:** This photo was taken looking south and shows a leaking valve on a storage tank.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010229**Orientation:** W**Date of Photo:** 03/12/2024**Time of Photo:** 4:37 PM**Latitude:** 33.34024**Longitude:** -92.68936**Photographer:** Uma Lad**Description:** This photo was taken looking west and shows an uncapped and open secondary containment discharge pipe containing a flowline.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010230**Orientation:** W**Date of Photo:** 03/12/2024**Time of Photo:** 4:37 PM**Latitude:** 33.34030**Longitude:** -92.68937**Photographer:** Uma Lad**Description:** This photo was taken looking west and shows standing water with an oil sheen below a flowline.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010232**Orientation:** N**Date of Photo:** 03/12/2024**Time of Photo:** 4:39 PM**Latitude:** 33.34033**Longitude:** -92.68953**Photographer:** Uma Lad**Description:** This photo was taken looking north and shows the facility sign at T.D. Murphy Tank Battery.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 7

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010234**Orientation:** SSE**Date of Photo:** 03/12/2024**Time of Photo:** 4:40 PM**Latitude:** 33.34041**Longitude:** -92.68948**Photographer:** Uma Lad**Description:** This photo was taken looking south-southeast and shows an uncapped and open secondary containment discharge pipe containing a flowline. Oil staining is present below the discharge valve.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 8

Location: 33.34011, -92.68934		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010235**Orientation:** W**Date of Photo:** 03/12/2024**Time of Photo:** 4:41 PM**Latitude:** 33.34040**Longitude:** -92.68957**Photographer:** Uma Lad**Description:** This photo was taken looking west and shows a transfer pipe with no catchment. Oil-stained soil surrounds the transfer pipe.