

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/31/2024	Time	13:50	
Inspection Due	2022-10-06T00:00:00Z	Operator Representative	White Palace Energy, LLC			
Operator Info	White Palace Energy, LLC 16210 Wind Hill Circle Skiatook, OK 74070 Phone: 918-396-7396	Inventory ID	OS5050000			
		API Well No				
		Lease Name	STUART			
		Well ID	4-A			
Location	NW 29 23N 11E	Status	Inactive	Well Type	Enhanced Recovery	
Latitude	36.444203	Longitude	-96.150463			
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	White Palace Energy, LLC			
Inspect No.		Date Last MIT	09/06/2022	Last Test Result	Fail	
Casing	4.5	Tubing		USDW		
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	N Inactive N N N N	Tubings	Annulus	AUTHORIZED		
		Fittings	N	N	Max Pressure	850
		Actual Pressure	0	0	Max Volume	12000
		Determined?	Open Hole	Open Value	Max Inj Units	Barrels Per Month
		Static Fluid Level	228.54			
		Determined?	Echo Meter			
		Injection Rate (bpd)				
Inspection Comments	Inspector observed the tubing fluid level to be 228.54 feet below the top tubing collar. The well was disconnected and not injecting. The well was overdue for MIT at the time of the inspection. The well sign was not updated to reflect the current operator.					
Inspector Signature						
Supervisor Signature (acting)						

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.444203, -96.150463		
City: Avant	County/Parish: Osage	State: Oklahoma




Photo File Name: R0010276

Orientation: WNW

Date of Photo: 01/31/2024

Time of Photo: 1:50 PM

Latitude: 36.444203

Longitude: -96.150463

Photographer: Matthew Allen

Description: This was well OS5050000 with the EPA Echometer attached. I observed the tubing fluid level to be 228.54 feet below the top of the tubing collar. The well sign was not updated to reflect the current well owner information.