



DOW CHEMICAL U.S.A.

PLAINTIFF'S EXHIBIT

DOW-756

TEXAS OPERATIONS
FREEPORT, TEXAS 77541

January 17, 1986

W. J. Landry
Craft Training, C-104

cc: C. K. Browdy, B-101
R. L. Daniel, B-101
G. G. Hinojosa, B-3501
J. E. Jackson, APB
J. E. Oswalt, B-106
J. H. Saunders, B-101
J. L. Seth, B-101
C. M. Simmons, B-201
D. H. Swisher, B-101
L. H. VonCannon, B-401
IHS File

RECEIVED

FEB 05 1986

R. L. DANIEL

ST0015046

EXPOSURE TO FRIABLE ASBESTOS FIBERS DURING RENOVATION AT C-107 STOCKROOM
IHS File CI-2696P

On December 30th and 31st, 1985 and January 2, 1986 stockroom employees, carpenters and contractors were exposed to friable asbestos fibers during renovation of C-107.

The renovation job at C-107 was being done by Carpenter Shop personnel, B-106. Contractors from the Yard and Utility Department were dismantling some stockroom shelves in the area while the renovation work was being done. A contractor electrician was also present to deactivate electrical circuits in the building.

After approximately three days of working in the area and removing portions of the ceiling for air condition duct work, it was discovered that the stucco ceiling had been sprayed with 1/4" asbestos insulation. Industrial Hygiene Services and Environmental Services were notified and the job was discontinued until a permit could be obtained from the Texas Air Control Board to remove the asbestos insulation.

The loose asbestos insulation already removed was cleaned up and properly disposed of according to the Texas Operations Asbestos Handbook Guide. After the clean-up operations, air samples were taken to determine the asbestos levels inside C-107, since stockroom employees are still working in the back section of the building. The average concentration of airborne asbestos fibers was 0.009 fibers/cc. The highest level found was 0.012 fibers/cc.

SEPARATING UNIT OF THE DOW CHEMICAL COMPANY

Quality
Performance
Means More At Dow

W. J. Landry

-2-

January 17, 1986

After the asbestos removal permit has been granted, the asbestos removal operations will be conducted according to the Texas Operations Asbestos Handbook. Employees removing the asbestos insulation will be monitored by Industrial Hygiene Services.

The employees that were exposed to the asbestos fibers were notified and proper medical surveillance is being provided.

J. L. Bell
J. L. Bell
Industrial Hygiene Services

lr
2/3/86

ST0015045