

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	03/25/2025	Time	13:55
		Operator Representative	McCann Resources, Inc		
Operator Info	McCann Resources, Inc 1613 West 6th Street Bartlesville, OK 740033404 Phone: 918-337-4747	Inventory ID	OS2221000		
		API Well No			
		Lease Name	Parker		
		Well ID	W-88		
Location	SE 16 27N 12E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.812509	Longitude	-96.010687		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	McCann Resources, Inc		
Inspect No.		Date Last MIT	05/08/2018	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 215
Lease Status		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed well OS2221000. At the time of the inspection, the well was 4.5" casing reduced to 1" threads. The fluid level was observed at the surface by way of the leaking 2" cutoff valve which allowed saltwater to stand full inside the open piping. At the time of the inspection there was no well sign present identifying the well.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.812509, -96.010687		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010630

Orientation: SSE

Date of Photo: 3/25/2025

Time of Photo: 1:58PM

Latitude: 36.812509

Longitude: -96.010687

Photographer: Matthew Allen

Description: This was well OS2221000 at the time of the inspection. The well was casing reduced to 1-inch pin threads. The fluid level was observed at the surface by way of leaking valve.