



Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	03/12/2024	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Jerry Langley Oil Company, LLC	
Facility Name:	Flowline Spill	
Facility Physical Location:	Latitude: 33.34146, Longitude: -92.68676	
(city, state, zip code)	Smackover, AR, 71724	
Mailing address:	100 East 7 th Street	
(city, state, zip code)	Smackover, AR 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-3042	
Facility Contact:	Jerry C. Langley jloc58@yahoo.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002237	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Kerri McCabe	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Michael Blaha	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Michael Blaha, Kerri McCabe, and I, Uma Lad, arrived at a flowline spill located off a lease road near All Gulf Road (33.34146, -92.68676) at 2:30 PM on March 12, 2024, for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on a crude oil spill along a lease road near All Gulf Road. The spill from the flowline is within a wetland that has surface connection to tributaries of Smackover Creek.

Section II - OBSERVATIONS

I observed loose oil on the east side of the lease road from a recent spill; see Appendix 1 (photo log), photo No. 1. For additional GPS location and photo metadata, see Appendix 1.

I also observed several areas with loose oil, oil sheen, and oil staining, see photo No. 2 through No. 4. I observed oil staining on trees, soil, and flattened vegetation, see photo No. 3.

The oil spill is located within a wetland, see photo No. 4 and No. 5.

Section III – AREAS OF CONCERN

No closing conference was held due to no Jerry Langley Oil Company, LLC staff being present during the inspection. The area of concern at the time of the inspection is the loose oil in the area.

Section IV – FOLLOW UP

The inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure area of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 5 photos taken on 3/12/2024

Appendix 1

Photograph Log

5 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.34146, -92.68676		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010206**Orientation:** E**Date of Photo:** 03/12/2024**Time of Photo:** 2:34 PM**Latitude:** 33.34160**Longitude:** -92.68681**Photographer:** Uma Lad**Description:** This photo was taken looking east and shows an overview of the oil spill.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.34146, -92.68676		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010205**Orientation:** W**Date of Photo:** 03/12/2024**Time of Photo:** 2:31 PM**Latitude:** 33.34146**Longitude:** -92.68676**Photographer:** Uma Lad**Description:** This photo was taken looking west and shows an oil sheen and oil staining on flattened vegetation.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.34146, -92.68676		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010207**Orientation:** WSW**Date of Photo:** 03/12/2024**Time of Photo:** 2:38 PM**Latitude:** 33.34133**Longitude:** -92.68665**Photographer:** Uma Lad**Description:** This photo was taken looking west-southwest and shows oil staining on trees, soil, and flattened vegetation surrounded by loose oil.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 33.34146, -92.68676		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010208**Orientation:** SW**Date of Photo:** 03/12/2024**Time of Photo:** 2:38 PM**Latitude:** 33.33261**Longitude:** -92.50759**Photographer:** Uma Lad**Description:** This photo was taken looking southwest and shows oil sheen on flattened vegetation within a wetland.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: 33.34146, -92.68676		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010209**Orientation:** E**Date of Photo:** 03/12/2024**Time of Photo:** 2:39 PM**Latitude:** 33.33261**Longitude:** -92.50759**Photographer:** Uma Lad**Description:** This photo was taken looking east and shows wetlands near the oil spill.