

Monsanto

FROM (NAME & LOCATION)

J. M. Gatewood

DATE

April 10, 1985

SUBJECT

Second Quarter
Safety and Housekeeping Inspection

REFERENCE

TO

R. H. Benson
D. N. Campbell
B. P. Curtis
R. M. Fritz
R. M. Gibbs
Phil Johnson
J. R. McGinty

D. K. Pease
R. R. Purgason
W. R. Rolingson
A. K. Uriarte
K. S. Wogoman

cc: G. Bostick
W. M. Haynes
W. G. Juhl
P. K. Saunders
D. R. Wise
G. L. Wofford

Inspection Team:
G. W. Daues
Glenn Olson
L. Inskeep

SHAC
D. Barfoot
R. Coleman
J. Gatewood
B. Hammann
B. Sanders
R. Sharp

The Second Quarter competitive Safety and Housekeeping Inspection for the lab area was conducted on April 9, 1985. The Quality Assurance Lab will be given the outstanding award and the best rating for this quarter. While the Research III area did just get into the outstanding level the inspection team did not feel that it should merit an award plaque. Ratings were:

Quality Assurance Lab	-	Outstanding
Research III	-	Outstanding
Research II	-	Good
Research I	-	Good

GENERAL COMMENTS

- Many of the rooms in Research I and Research II buildings are in need of interior painting and window glazing.
- Several labs were very cluttered and housed more apparatus than available storage space.
- Several labs were vacant with apparently no one responsible for housekeeping or cleanup.
- Emergency utility cut-off drawing in Research I and Research II halls have not been revised in twelve years - need to check to make sure they are current and revise date.

QUALITY ASSURANCE LAB

- North Lab Old 2" solvent line on outside of building is badly corroded and needs to be removed.
Kitchen area - ice box needs to be straightened up.

RESEARCH III - PETS

- Designated areas or boxes need to be provided for face shields.
Area in back lab where bar stock and metal is stored needs to be straightened up.

RESEARCH II

- Conference Room Boxes stored on floor.
- Lobby Respirator fit sign - loose on wall.
- Hall by Storeroom 1/2 copper tubing loose and hanging
- Back of Building Plectron radio turned off.
First Floor
- Research Store- Eyebath and safety shower not accessible.
room
- Lab 2105 Lab crowded and cluttered.
- Lab 2113 General clutter in lab and office.
Hood door too high.
- Lab 2114 Lab dirty, lapp pumps dripping oil on floor.
- Lab 2142 Emergency card on door needs to be updated.
- Lab 2143 Emergency card needs updated.
Hood above recommended set point.
Many samples on counter.
Ladder should be stored.
Need coat rack.
- Lab 2145 Shelves need straightening up.
- Lab 2148 Hole in window.
- Cell 3 and Water dripping on floor.
Bench 2
- Lab 2106 Beaker of material on shelf covered with
aluminum foil.
- 2140 Trash in corner.
Xerox Room Scott air paks - need inspection
- Lab 2128 Glass bottle for drain - could be kicked over.

RESEARCH II Cont'd.

- Lab 2136 Need N₂ hose rack south side of lab.
- Air Condition Building Trash in south side.
- High Pressure Lab Radioactive material drum - has corrosion.
- Maintenance Shop Need boxes for face shields.
- Cell Areas Ladder wired off to pipe.

RESEARCH I

- Main Entrance Cracked window.
Needs painting.
- Lab 1109 Calculator plugged in hood.
Paper cutter no latch - second violation.
- Lab 1105 Name on door tag out of date.
- Lab 1204 Clutter on floor.
Drawers need to be straightened.
- Lab 1205 Painting and caulking of windows.
- Lab 1206 Window broken.
Need clothes rack.
- Lab 1308 Needs to be straightened up.
Electron radio turned off.
- 3rd Floor Stock room wire hanging outside conduit .

Please respond to the comments in your area to W. G. Juhl, R. L. Hammond, G. Bostick, and Doug Barfoot by May 15, 1985.

Jem/m

J. M. Gatewood, SHAC
For the Inspection Team:

G. Daues
G. Olson
L. Inskeep
B. Hammann

SC

000341

LAM001538