

FRICTION MATERIALS STANDARDS INSTITUTE
588 MONROE TURNPIKE, MONROE, CT 06468

AUTOMOTIVE DATA BOOK BULLETIN #4-981
December 4, 1998

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>				
1999, TL		7656-D787**	D/	
		(Notes #3 & #8)		
<u>AM GENERAL</u>				
1998-97, Hummer		7658-D788**	D/D	7658-D788**
		(Notes #5 & #9)		
	OR	7531-D651**	D/D	7531-D651**
1996-95, Hummer		7531-D651**	D/D	7531-D651**
<u>BUICK</u>				
1999, Century		7574-D699**	D/N	1487-S636
	OR		/D	7387-D698**
1999, LeSabre		7384-D623**	D/N	1487-S636
1999, Park Avenue		7574-D699**	D/D	7387-D714**
1999, Regal		7574-D699**	D/N	1487-S636
	OR		/D	7387-D698**
1999, Riviera		7574-D699**	D/D	7387-D714**
<u>CADILLAC</u>				
1999, Catera		7588-D720**	D/D	7582-D709**
1999, Deville		7574-D699**	D/D	7387-D714**
	OR	7259-D369**	D/BH	2134BTT-S652
1999, Eldorado		7574-D699**	D/D	7387-D714**
1999, Seville		7621-D753**	D/D	7622-D754**
<u>CHEVROLET</u>				
1999, Camaro		7618-D749**	D/D	7619-D750**
1999, Cavalier		7554-D673**	D/BH	2164-S719
1999, Corvette		7599-D731**	D/D	7600-D732**
1999, Lumina		7265-D376**	D/N	1487-S636
	OR		/D	7387-D714**
1999, Malibu		7620-D752**	D/N	1496-S720
1999, Metro		7331-D451**	D/N	1489-S724*
	OR		/N	1461-S732*
1999, Monte Carlo		7265-D376**	D/N	1487-S636
	OR		/D	7387-D714**
1999, Prizm		7611-D741**	D/N	8105-597*
1998, Prizm		7611-D741**	D/	
1999, Venture		7574-D699**	D/N	1394-S636
	OR		/D	7387-D698**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the
Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>CHEV TRUCK/GMC TRUCK</u>				
Astro Van/Safari Van	1999	7214A-D52	D/BH	2117BTT-S651
Astro Van4WD/Safari Van4WL	1999	7259-D369**	D/BH	2117BTT-S651
Blazer/Jimmy	1999	7480A-D202	D/BH	2117BTT-S651
	OR	7593-D726**	D/D	7596-D729**
C1500/C1500	1999	7259-D369**	D/N	1404A-S675
C2500/C2500	1999	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
C3500/C3500	1999	7260-D370**	D/BH	2042BT-S655
	OR	7339-D459**	D/BH	2157AT-S656
C3500 DRW/C3500 DRW	1999	7339-D459**	D/BH	2157AT-S656
	OR	7815-D380**	D/D	7815-D380**
Express Van G1500/ Savana G1500	1999	7259-D369**	D/BH	2073AT-S653
Express Van G2500/ Savana G2500	1999	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
Express Van G3500/ Savana G3500	1999	7260-D370**	D/BH	2157AT-S656
	OR	7339-D459**	D/	
K1500/K1500	1999	7259-D369**	D/N	1404A-S675
	OR		/BH	2073AT-S653
K2500/K2500	1999	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
	OR	7339-D459**	D/BH	2157AT-S656
K3500/K3500	1999	7260-D370**	D/BH	2157AT-S656
	OR	7339-D459**	D/	
S10/Sonoma	1999	7480A-D202	D/BH	2117BTT-S651
Suburban1500/Suburban1500	1999	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
	OR		/BH	2157AT-S656
Suburban2500/Suburban2500	1999	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
	OR	7339-D459**	D/BH	2157AT-S656
Tahoe/Yukon	1999	7259-D369**	D/N	1404A-S675
	OR	7260-D370**	D/BH	2073AT-S653
Tahoe Police/Yukon Police	1999	7260-D370**	D/BH	2073AT-S653
<u>CHRYSLER</u>				
1999, 300M		7623-D730**	D/D	7650-D782**
1999, Cirrus		7530A-D650	D/N	1481-S716*
	OR		/D	7438B-D641
1999, Concorde		7623-D730**	D/D	7438A-D658
1999, LHS		7623-D730**	D/D	7438A-D658
1999, Sebring		7365-D484**	D/N	1445-S658
	OR		/D	7272-D383**
1999, Sebring Convertible		7530A-D650	D/N	1449-520
	OR		/D	7438B-D641
1999 Town & Country		7470A-D642	D/N	1485ATT-S714
	OR		/D	7424-D751**

		FRONT	SYSTEM	REAR
		FMSI NO.	F/R	FMSI NO.
<u>DODGE</u>				
1999, Avenger		7365-D484	D/N	1445-S658*
	OR		/D	7272-D383**
1999, Intrepid		7623-D730**	D/D	7438A-D658
1999, Neon		7597-D730**	D/N	1473-S689*
	OR		/D	7438-D759**
1999, Stratus		7530A-D650	D/N	1481-S716*
	OR		/D	7438B-D641
1999, Caravan		7470A-D642	D/N	1485ATT-S714
	OR		/D	7424-D751**
1999, Grand Caravan		7470A-D642	D/N	1485ATT-S714
			/D	7424-D751**
<u>GMC TRUCK</u>				
Envoy	1999	7593-D726**	D/D	7596-D729**
<u>HENDRICKSON TRAILER</u>				
All Models	1997		/A	4515E
	OR		/A	4515G
All Models	1996		/A	4515G
<u>INTERNATIONAL</u>				
1600 Series				
1652SC	1998	7654-D786**	D/D	7654-D786**
		(Notes #1 & #7)		
	OR	7654-D786**	D/D	7655-D786**
				(Note #2)
	OR	7655-D786**	D/D	7655-D786**
3000 Series School Bus				
3000FE, 3400, 3600SC,				
3800SC	1998	7654-D786**	D/D	7654-D786**
	OR	7654-D786**	D/D	7655-D786**
	OR	7655-D786**	D/D	7655-D786**
4000 Series				
4700 4x2, 4700LP 4x2,				
4900 4x2	1998	7654-D786**	D/D	7654-D786**
	OR	7654-D786**	D/D	7655-D786**
	OR	7655-D786**	D/D	7655-D786**
<u>ISUZU</u>				
1999, Hombre		7480A-D202	D/BH	2117BTT-S651
	OR	7593-D726**	D/	
1999, Trooper		7459-D579**	D/D	7460-D580**
<u>LINCOLN</u>				
1998, Continental		7633-D765**	D/	
<u>MERCEDES (See Comments)</u>				
1998, C230			/D	7657-D779**
				(Note #4)
1998, C280			/D	7657-D779**

December 4, 1998

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
OLDSMOBILE			
1999, Aurora	7574-D699**	D/D	7387-D714**
1999, Intrigue	7574-D699**	D/D	7387-D698**
1999, 88	7384-D623**	D/N	1487-S636
1999, Silhouette	7574-D699**	D/N	1487-S636

PONTIAC

1999, Bonneville	7384-D623**	D/N	1487-S636
1999, Firebird	7618-D749**	D/D	7619-D750**
1999, Grand Prix	7574-D699**	D/D	7387-D698**
1999, Sunfire	7554-D673**	D/BH	2164-S719
1999, Montana	7574-D699**	D/N	1394-S636
OR		/D	7387-D698**

SATURN

1999, All	7595-D728**	D/N	1437-S637*
OR		/D	7387-D714**

SUZUKI

1999, Esteem	7557-D677**	D/N	1461-S630*
1999, Grand Vitara	7559-D680**	D/N	1506-S738*

(Notes #6 & #10)

VOLKSWAGEN

1998, Beetle		/D	7335-D340**
--------------	--	----	-------------

COMMENTS

Existing shoe with new lining:

Shoe	Assembly	Application
D779	7657-D779	1998 Mercedes C230, C280 Rear

CORRECTIONS**FMSI 7645-D778 has been canceled. See 7630-D762.**

1998 Catalog shows Lincoln Continental front as FMSI 7476-D598.
The correct listing is FMSI 7633-D765.

DISC BRAKE LINING ASSIGNMENTS

Note #1	FMSI 7654	7654-D786		
7654	60.0 20.3	225.0	4	Integrally
	(2.36 .799	8.86)		Molded
(D786)				
International				
Note #2	FMSI 7655	7655-D786		
7655	60.0 26.8	225.0	4	Integrally
	(2.36 1.055	8.86)		Molded
(D786)				
International				

DISC BRAKE LINING ASSIGNMENTS (cont'd)

Note #3	<u>FMSI 7656</u>	7656-D787		
7656	51.8 17.3	124.5	4	Integrally
	(2.04 .681	4.90)		Molded

(D787)

Acura

Note #4	<u>FMSI 7657</u>	7657-D779		
7657	46.5 14.8	59.7	4	Integrally
	(1.83 .583	2.35)		Molded

(D779)

Mercedes

Note #5	<u>FMSI 7658</u>	7658-D788		
7658	47.0 14.6	161.8	4	Bonded
	(1.85 .575	6.37)		

(D788)

AM General

DRUM BRAKE LINING ASSIGNMENTS

Note #6	<u>FMSI 1506</u>	1506-S738		
1506	220.0	39.6 4.6	210.0	4 Bonded
	(8.66	1.56 .181	8.27)	

(S738)

Suzuki

DISC BRAKE SHOE ASSIGNMENTS

Note #7	<u>FMS D786</u>			International
	244.0	Plate 7.9		
SHOE D786	(9.61)	(.311)		
7654				
7655				

	Inner -			Acura
Note #8	<u>FMS D787</u>			
	149.1	Plate 6.6		
SHOE D787-I	(5.87)	(.260)		
7656				
Sensors staked-on (LH,RH)				

DISC BRAKE SHOE ASSIGNMENTS (cont'd)

Outer -	
<u>FMS D787</u>	Acura
149.1 Plate 6.6	
SHOE D787-O (5.87) (.260)	
7656	

	
Note #9	<u>FMS D788</u>
176.8 Plate 5.4	AM General
SHOE D788 (6.96) (.213)	
7658	

DRUM BRAKE SHOE ASSIGNMENTS

	
Note #10	<u>FMS S738</u>
220 x 40 (Web 4.1)	Suzuki
SHOE S738 (8.66 x 1.57) (.161)	
1506	

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover, SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute Inc, 588 Monroe Turnpike, Monroe, Connecticut 06468.