

The time and date stamp for these photos are incorrect, the inspection occurred on November 7, 2023 beginning at 11:29 AM.



Photograph 1. Presby Recycling 11/6/2023 23:30 DSCN0604.JPG
Description: Facility Sign.



Photograph 2. Presby Recycling 11/6/2023 23:40 DSCN0605.JPG
Description: View of the Ham Branch looking southwest from the Facility's western perimeter. The solid blue line depicts flow direction.



Photograph 3. Presby Recycling 11/6/2023 23:40 DSCN0606.JPG
Description: View of the Ham Branch looking southwest from the Facility's western perimeter.



Photograph 4. Presby Recycling 11/6/2023 23:42 DSCN0607.JPG
Description: View of scrap batteries stored undercover, on a pallet, with the two levels separated by cardboard boxes.



Photograph 5. Presby Recycling 11/6/2023 23:44 DSCN0608.JPG
Description: The Facility's aluminum bailer.



Photograph 6. Presby Recycling 11/6/2023 23:45 DSCN0609.JPG
Description: View of baled aluminum stored under cover.



Photograph 7. Presby Recycling 11/6/2023 23:46 DSCN0610.JPG

Description: View of the Facility's copper smelter that has not been in use due to air permitting challenges.



Photograph 8. Presby Recycling 11/6/2023 23:47 DSCN0611.JPG

Description: View of 55-gallon plastic waste oil drums stored in a shed, within secondary containment.




Photograph 9. Presby Recycling 11/6/2023 23:47 DSCN0612.JPG

Description: View of 55-gallon used oil drums stored in a shed. The drums were labeled “used oil” and stored in secondary containment.



Photograph 10. Presby Recycling 11/6/2023 23:47 DSCN0613.JPG


Description: Additional view of 13 55-gallon drums holding waste oil stored undercover, within secondary containment, seen in Photographs 8 and 9.



Photograph 11. Presby Recycling 11/6/2023 23:48 DSCN0614.JPG
Description: View of empty 55-gallon drums and totes stored in a shed.



Photograph 12. Presby Recycling 11/6/2023 23:51 DSCN0615.JPG
Description: Metal turnings (yellow bucket) being drained into the blue bucket and a used oil drum. The buckets were under cover and on a containment pallet.



Photograph 13. Presby Recycling 11/6/2023 23:51 DSCN0616.JPG

Description: View of the Facility's transfer tank, located inside the garage. The transfer tank is equipped to drain gasoline from equipment or end-of-life vehicles (ELVs) and dispense gasoline.



Photograph 14. Presby Recycling 11/6/2023 23:54 DSCN0617.JPG

Description: View of the garage used for equipment maintenance.




Photograph 15. Presby Recycling 11/6/2023 23:56 DSCN0618.JPG

Description: View looking north along the Facility's western perimeter adjacent to Ham Branch. Heavy equipment, empty roll-off dumpsters, and a truck-mounted asphalt hot box were parked on the western perimeter. The dashed blue line depicts the estimated stormwater flow direction.




Photograph 16. Presby Recycling 11/6/2023 23:56 DSCN0619.JPG


Description: View of ferrous metals stockpiled on the eastern side of the yard and pooled stormwater in the center of the yard.



Photograph 17. Presby Recycling 11/6/2023 23:56 DSCN0620.JPG
Description: View looking south toward the office from the same location as Photograph 16.




Photograph 18. Presby Recycling 11/6/2023 23:57 DSCN0621.JPG
Description: View looking west at Ham Branch from the Facility's western perimeter. Ham Branch is barely visible through the vegetation. Scrap steel guard rails were on the ground in this location.




Photograph 19. Presby Recycling 11/6/2023 23:58 DSCN0622.JPG

Description: View of a truck-mounted asphalt hot box stored on the western perimeter, adjacent to Ham Branch.



Photograph 20. Presby Recycling 11/7/2023 00:00 DSCN0623.JPG

Description: View of Ham Branch looking northwest from the side of the truck-mounted asphalt hot box. A discrete conveyance path is indicated by the blue dashed arrow and sediment deposition on the east bank of Ham Branch is circled in red.



Photograph 21. Presby Recycling 11/7/2023 00:00 DSCN0624.JPG
Description: View looking upstream from Photograph 20.



Photograph 22. Presby Recycling 11/7/2023 00:02 DSCN0625.JPG
Description: View of used tires baled together used as a fence on the north side of the property.




Photograph 23. Presby Recycling 11/7/2023 00:02 DSCN0626.JPG

Description: View of the rack on the north side of the property that the Facility previously used to lift and drain ELVs. The rack was replaced with the transfer tank pictured in [Photograph 13](#).



Photograph 24. Presby Recycling 11/7/2023 00:04 DSCN0627.JPG

Description: View of piles of metal shavings accumulating in truck beds.



Photograph 25. Presby Recycling 11/7/2023 00:10 DSCN0628.JPG

Description: View of scrap engines placed in a roll-off dumpster on the east side of the ferrous metal stockpile. Corrugated steel covered this dumpster.