

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	05/27/2025	Time	11:10
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS0284000			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name NBU			
	Allen, TX 75013	Well ID 27-W23			
	Phone: 832-300-8221				
Location	NW 18 27N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.820724	Longitude	-96.70116		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection		CapturePoint, LLC	
Inspect No.		Date Last MIT			
Casing	4.5	Tubing			
Monitoring Device Elected	N	Tubings	Annulus	AUTHORIZED	
Monitoring Device		Fittings	N	N	Max Pressure 804
FLM Canister Pressure		Actual Pressure		Max Volume	
Lease Status	Active	Determined?		Max Inj Units	Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments		Inspector observed the well location after surface restoration was completed. There were no areas of concern at the time of the inspection.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.820724, -96.70116		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010675

Orientation: ESE

Date of Photo: 5/27/2025

Time of Photo: 11:11 AM

Latitude: 36.820724

Longitude: -96.70116

Photographer: Matthew Allen

Description: This was the location of well OS0284000 after surface restoration was completed.