

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/16/2025	Time	09:10
		Operator Representative	CapturePoint, LLC		
Operator Info	CapturePoint, LLC 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS0586000		
		API Well No			
		Lease Name	NBU		
		Well ID	100-W4		
Location	SW 01 26N 05E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.75583	Longitude	-96.716948		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	09/19/1988	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 775
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed the location of well OS0586000. At the time of the inspection, surface restoration was complete.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.75583, -96.716948		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010564

Orientation: NNE

Date of Photo: 1/16/2025

Time of Photo: 10:07 AM

Latitude: 36.75583

Longitude: -96.716948

Photographer: Matthew Allen

Description: This was the well location of OS0586000 with the casing cutoff and capped 3 feet below the land surface. Surface restoration completed.