

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/15/2023	Time	10:05
Inspection Due		Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS2883000		
		API Well No			
		Lease Name	NRU		
		Well ID	20W8		
Location	SE 21 24N 07E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.540526	Longitude	-96.556207		
Inspection Reason	MIT	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	11/02/2017	Last Test Result	Acceptable
Casing	5.5	Tubing	2.375	USDW	
Monitoring Device Elected		Tubings	Annulus	AUTHORIZED	
Monitoring Device		Fittings	N	N	Max Pressure 685
FLM Canister Pressure		Actual Pressure	45	0	Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	Inspector witnessed Standard Annulus Pressure Test (SAPT) on well OS2883000. Pressure, hold OK. I observed no areas of concern at the time of the inspection. EPA enforcement staff will review inspection data to determine compliance with EPA UIC regulations. Rose Malanga, Nick Bruno and Mike McFadden (Lead) participated during the inspection as part of the On the Job Training requirement associated with the SDWA/UIC inspector credentialing process. Initial: 295psi Mid: 295psi Final: 293psi Pressure Hold OK Total flowback: 4200ml Packer Depth: 2447'				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.540526, -96.556207		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010070

Orientation: W

Date of Photo: 02/15/2023

Time of Photo: 10:14 AM

Latitude: 36.540526

Longitude: -96.556207

Photographer: Matthew Allen

Description: This was well OS2883000 at the time of the inspection.