

Date of Inspection: June 1999Quarter of Inspection: Second Quarter**VCM BLEEDER VALVE INSPECTION**

Area / Location	P&ID #	Description	Bleeder Valve / Plug #	Comments	Checked and Corrected
VS	90102	3 in. line from Tank Cars 3 & 8	3 BV	Pressure gauge leaking	JDY
VS	90111	Under cylinder at PP-710	8 P	Plug leaking	JDY
OM	90104	Top of RX-500	4 P	Entire gauge assembly loose	JDY
OM	90105	Top of RX-600	5 P	PI w/o plug	JDY
OM	90105	Top of RX-600	2 P	Plug leaking	JDY
OM	90106	Top of RX-700	8 P	Entire gauge assembly loose, Vent #4	JDY
OM	90108	On Vent from Dump Strainers	7 BV	Cover missing	JDY
OM	90108	PP-490 Suction line	10 BV	Plug missing	JDY
OM	90108	PP-489 Suction line	12 BV	Plug missing	JDY
OM	90109A	CP 506	1 BV	Plug missing	JDY
OM	90110	Underside of EX-005	2 BV	PI leaking	JDY
OM	90110	FL-020E	11 BV	Plug leaking	JDY
OM	90112	FL-691	8 P	Gauge and plug missing	JDY
OM	90114	Underside DM-703	12 BV	Valve leaking	JDY
OM	90119	DM-802	12 BV, 14 BV	Plugs missing	JDY
OM	90134	PP-500	12 BV	Cover plate missing	JDY
OM	90134	Line to Dump tank DM-075	2 BV	Plug missing	JDY
OM	90136	PP-511	9 BV	Cover loose	JDY
NM	90100	Underside of DM-745	19 BV	Leaking plug	JDY
NM	90109	PP-889 North	21 BV	Illegal hose connection	JDY
NM	90111	EX-334 inlet line	3 BV	Illegal hose connection	JDY
NM	90115	FL-386 housing	19, 20 BV	Illegal hose connections	JDY
NM	90132	EX-012	4 BV	Plug loose	JDY
NM	90134	PP-506 suction line	7 BV	Cover missing	JDY
NM	90134	FL-016,017 outlet line	1 BV	Cover loose	JDY
NM	90139	PP-502 suction line	7 BV	Cover missing	JDY
NM	90141	FL-033	2 BV	Plug missing	JDY

Document: k:\iso\14000\env\E10.xls

Description: VCM Bleeder Valve Inspection

Form E10

Page 1 of 2

Last Revised: 11/10/98

Last Printed: 8/23/99

ABD00079882

VCM BLEEDER VALVE INSPECTION

NM	90142	EX-010 inlet	9 BV	Leaking plug	JDY
NM	90143	Underside of RX-746	1 BV	Plug missing	JDY

Note: All other bleeder valves and plugs were inspected and found in satisfactory condition.

**NM - New Module
OM - Old Module
VS - Sphere
DY - Incinerators**