



Fig. 6 Renewing of municipal truck brake linings by light grinding to remove grease and dirt.

*This figure appears to be the one to illustrate beveling and the dust pile accumulated. If so, there is no figure illustrating light grinding, since Figure 5 is merely the reverse of this one.*

8005 1897

PRODUCED BY FORD