approximately 10%. There is no evidence of asbestos dust in connection with these parts.

6. Powerhouse - The gaskets used for pipe connections in the Powerhouse are asbestos containing parts. Fourteen (14) employes have an exposure time of less than 1%. The material used for pipe coating does not contain asbestos per Plant Engineering personnel.

The only operation of those reviewed that would give any appearance of potential health hazard was the Commercial Heat Shield. Because this appeared to be a potential problem, we asked Libardo LaTorre, Industrial Hygienist, for Central Hygiene to conduct a study of the area. Results of the study, which are attached, indicate there is no problem.

D. P. Obringer,
Safety Engineer

DPO/ejs

Attachments

COATES V FORD - 2117

PRODUCED BY FORD IN COATES