PLAINTIFF'S EXHIBIT

MON-823

Monsanto

FROM (NAME & LOCATION) Texas City, Texas

DATE : May 9, 1975

SUBJECT : PLANT MANAGER'S SAFETY BOARD AGENDA
Friday, May 16, 1975

REFERENCE :

TO : Plant Manager's Safety Board

cc: Brubaker, Lane, Rosenberg, Danner, Peters, Marsh, Clarke for Jones, Ryan, Gilmore, McCullough, Trafton, Fuller, Marshall for Davis, Hamby, Jones.

The following is the agenda for the Plant Manager's Safety Board meeting to be held Friday, May 16, at 10:15 a.m. in the Cafeteria Conference Room.

1. Safety Program Revision - Status report

   A. Bulletin P-0100. Being prepared for distribution.

   B. Election of unit/craft safety representatives. –

   C. The logo board for installation at both gates.

   D. Revision of the present safety sign board at both gates.

2. Hourly Safety Committee items from meeting of April 29, 1975.

   A. The treated water pumps at Power 2 drain to the pad. An MRO was written to pipe these to the sewer but instead the area was painted with non-skid paint. It is still slippery and messy.

   B. The utility water outlet on the South side of No. 9 boiler runs hot (steaming), probably because it is next to and and insulated with a steam line.

   C. In the warehouse at NW corner of Department 19, pallets are used as floor for drum storage. Laborers have turned their ankles when walking across these pallets.

   D. Crane booms should have lights or be painted so that they can be seen at night.

   E. Silo storage tanks in Department 42 are either not provided with level shut-offs or the existing shut-offs do not work.

   F. The Charles Martin people are using wire to secure tags to sample containers. The wires are hazardous, and it is suggested that they use string.

   G. Steam traps North of 17 Compressor House should be provided with a pot.

WSC Items go to SHAC leave off agenda.

SC 14167

STG 2431012

LAM015956

H. Tank with platform located at NE corner of Warehouse C is badly deteriorated.

I. Taxi backed over "deadman" in Dock 5 area.

J. Vehicle drivers not paying attention to stripped area on Second Ave. S. (specific License KBL-57).

K. When Queeny was loaded recently, the naphthalene vapors were very strong in Carpenter Shop.

C. L. Gilmore

CLG/gk

SC

14168

STG 2431013

LAM015957