PLAINTIFF'S EXHIBIT

KRC-524

Asbesto incident Report.

February - 22 - 1988

During sulfolane unit Turn around, two Repcon Contruction Co. workers were send to removed the chanel head of SU-E-24 exchanger. When they were working on the exchanger the insulation on the head was on their way and they start tearing down leting the insulation fall in the ground.

I happen to be on the area when they start doing this, I told them to stop and get out of the area becaus that insulation look like asbestos to me.

We fallow the propper Asbestos removal procedure for the clean up.

1H 053991

A sample was taken and the results indicated that it was asbestos.

we talk to Shen Ely and ask him to talk to the Repcon forman and let them know that only S.W.O.R. insulators are suppose to removed insulation on this areas. Shen said that they knew and that this incident was the result of a missunderlanding.

Luis Miranda
3/7/88

SWRf/Asbestos 6649