APPROVAL:
Ind. H. A. Eschenbach
Hyg.
Tech. D. O'Donnell dod
Admin.
Q. Assur. R. C. Ericson

PRODUCT CODE NO. 41-06-04-1-19
THIS DRAFT CANCELS PRIOR DRAFT NO. ET-604
(1) AT (2) (2) (4)

PRODUCT MONOKOTE 5 (716) (K3D18)
PLANT NAME Trenton
DRAFT NO. ET-619
DATE January 29, 1981

In case of an accident or any other emergency, call CHEMTREC at 800-424-9300 for instructions on handling hazardous materials. CHEMTREC operates 24 hours per day, 7 days per week.

PACKAGING:

CONTAINER SIZE	CPD SPEC. NO.	APPROX. NET SHIPPING WT.
alve-pack bag 25 x 29½ x 6	99-06-08-1-19	45#



LABELLING & STENCILLING REQUIREMENTS

	SIDE	TOP
Product	☐	☐
Special Warning Label	☐	☐
Keep From Freezing	☐	☐
Stir Well	☐	☐
Address	☐	☐
Other Stencil plant I. D. per Q. C. Operating Inst. A-2	☒	☐
	☐	☐

NOTES, SAFE PRACTICE & STORAGE

Saybolt Visc. _____

Flash Point

Pensky-Martens C.C. _____

Tagliabue C.C. _____

Setaflash _____

Vapor Pressure @ 100°F. _____

Handling & Storage Requirements _____

BILL OF LADING REQUIREMENTS

D.O.T. Class (1) .....

D.O.T. Article (2) .....

Freight Classification ...Wall plaster.....

Spec. B/L Marking .....

HAZARDOUS MATERIALS HANDLING INSTRUCTIONS

The following safety equipment is recommended for use where appropriate: respirators meeting MESA/NIOSH 21C requirements for dusts and 23C requirements for vapor, gas, mist, or fumes; chemical goggles with baffles & anti-fog treatment.

HAZARDOUS MATERIALS	SAFETY PRECAUTIONS
Vermiculite (B)	Kearney: Avoid breathing dust. Nuisance dust respirable fraction 5 mg/m³. Total dust 15 mg/m³.
MKAE (B,D)	May be irritating but not particularly toxic. Don't breathe dust. Use respirator. Avoid skin irritation by washing off with soap and water. No TLV set.

(1) Refer to D.O.T. Section 172.4
(2) Refer to D.O.T. Section 172.5

TLV = Threshold Limit Value (A concentration, usually airborne, of a substance to which a person may be safely exposed.) It may be expressed as a Time-Weighted-Average (TWA) for an 8-hour day and a 40-hour week, or in some cases as a ceiling limit (C).

15193321

DRAFT NO. ET-619 (716) PRODUCT MONOKOTE 5 (K3D13) BATCH NO. OR PLANT NAME Trenton

HAZARDOUS MATERIALS HANDLING INSTRUCTIONS

HAZARDOUS MATERIALS	SAFETY PRECAUTIONS
CELIB (F)	Nuisance dust. TLV = 10 mg/m^3. Spontaneous combustion if brought in contact with organic material (sawdust, turpentine, etc.). Use respirator.
WOCH (D*)	Causes temporary skin and eye irritation and dry throat. Avoid skin contact and breathing of fiber-laden air. Use respirator and wear gloves and goggles. Avoid scratching contaminated skin. Wash with cool water - TLV is 10 mg/m^3.