Monsanto

FROM (NAME & LOCATION) Anniston, Alabama

DATE Novmeber 15, 1968

cc: L. L. Faulkner
B. B. Hedleston
P. C. Herman

SUBJECT CEA 1430 & 1452 - Combined Check List
(not including Warehouse Production Area)

REFERENCE

TO : H. E. Waldrep

Since "Punch Lists" for 1430 are becoming so numerous and recent requests and sketches have been submitted to the field, this coglomerate list has been made to avoid confusion. The first ten items must be done A.S.A.P.

~~1) Funnel and drain piping at middle dock *~~

~~2) Funnel and drain piping at south dock *~~

~~3) Sample valve and spout to be added on pressure gage connection~~ at ~~discharge of each Aroclor pump in tank farm~~

~~4) One bad steam valve needs replacing at north dock~~

~~5) Air lines at each dock should be extended to tie into steam lines (below steam valve) in order to blow condensate out of tank car coils~~

6) ~~Mount Safety Shower signs and Eyewash Hoses (3 places in tank farm)~~

~~7) Mount air operated hoist over large sprinkler in blend area and connect to air supply.~~ ~~sketch submitted~~

8) ~~Funnel lines at docks will not function in winter without some tracing - locate shut off valve for easy accessibility and run tracing to trench drain~~

~~9) Insulate PP nozzles on tanks in tank farm~~

10) Water lines to steam head mixers at north and middle docks needs insulation

~~11) Scott Air Pak storage box *~~ NEEDS LETTERS

~~12) Stile over suction piping in tank farm *~~

~~13) Fix all steam leaks in tank farm~~

~~14) Replace faulty pressure gages at pump 710 and steam coils of tanks 704, 705 and 711~~

~~15) Isolate plate coils of tank 810 with appropriate valves~~

0357167

TOWOLDMON0044789

~~16) Pilsen drip pan *~~

~~17) Lock out board at M.B.C. *~~

18) Hanger for truck unloading hose *

~~19) Hanger for truck loading hose *~~

~~20) Insulate all outside HB-40 line~~

21) A faucet is needed at west side of office for hose (1452)

22) Handle for gas shut-off valve in W. H. most be wired to valve (1452)

23) Emergency gas shut-off wrench and signs *

* sketch submitted

24) The loading docks all need triangular plates welded to the hazard area (1452)

~~25) H_2O to the refrigerator ice machine in lunch room (1452).~~

26) Door to cleaning room needs fixing (1452)

27) Gutters still leak on office (1452)

~~28) Sink in washroom leaks at drain (1452)~~

~~29) 3rd rack level too high for fork lift - lower two notches (1452)~~

~~30) Rain protection at docks needs altering per OSD~~ IN PROGRESS

~~31) Downspout at middle dock needs revising to prevent washing gravel down steps~~

~~32) Downspout at south dock needs a splash block~~

DROP ~~33) Filter access stands in tank farm~~

DuBOLS ~~34) Install water and steam piping for cleaner at blend area~~

35) Install clay oven

~~36) Insulate clay addition pot~~

~~37) Guard for 727 blend tank agitator~~

~~38) Blow out to Solid Arcolor line at tank 707~~

TOWOLDMON0044790

39) Drainage at south end of truck loading pad unsatisfactory

~~40) Lower heaters in W. H. (per instructions from B. B. H.)~~ PKG. L/S

~~41) Rain shield over personnel gate~~

~~42) Compressor piping changes per Lamar Faulkner~~

~~43) Step needed at south end of R.R. for stairs~~

~~44) A rack mounted on north dock is needed to~~ hang flex hoses (will submit sketch)

V. T. Langdon

jw 45. OIL IN TK. FARM BUBBLERS

× 46. TRUCK [redacted] RAMP @ N. DOCK

X 47. LARGER RACK FOR AIR CYL.

? 48. 711 & 712 SAMPLE PORTS (INS.)

49. ACCESSWAY TO POROCEL COL.

50.

51.

52.

0357169

TOWOLDMON0044791