	NOTES AND REFERENCES
b. Where insulation is being replaced in an area of unknown asbestos content, identify the replacement insulation by a strip of tape placed around the circumference of the pipe furnish at strategic location on equipment pieces.	o See Figure 3 for tape specification.
I. CAUTION SIGNS AND LABELS	
1. Signs shall be at all approaches to areas where asbestos concentrations may be above permissible exposure limits. (See Figure 1.)	o The signs shall be placed at a sufficient distance to permit an employee to read the signs and take necessary precautions before entering the area.
2. Labels conforming to Figure 2 shall be used to identify containers of raw materials scrap, waste and other products containing asbestos.	
J. EPA REGULATIONS ON ASBESTOS	
1. The Environmental Protection Agency requires certain reporting procedures when operational facilities containing asbestos are being demolished. Reporting procedures are also required involving renovation of 80 meters (262.4 ft.) of pipe or more than 15 square meters (161.4 sq. ft.) of friable asbestos.	o This requirement does not pertain to transite siding because transite is not considered "friable".