FILE NAME: Rogers Corporation (ROG)

DATE: 0000

DOC#: ROG058

DOCUMENT DESCRIPTION: Handwritten Unsigned Notes

Head Design For Feeding Fiber into Carder
Cost of Dragger & Tubes -
Possibilities of Performing Analysis work if
Rogers Buys and Does Actual Testing. -
Noise Meter with Literature pertaining
to Noise Measurement and General
Description of Noise.

Cost of M.F. Sampling

Respiration Information - Dustfree

Barry,

In General Rogers Corporation Manchester was a
Real Mess Terrible housekeeping and attitude of the Employees
as well as the County people left alot to be
desired the area of Environmental Control

#1 Milling Area.
A.) Room very poor housekeeping exist. Pre-
mix operation dump chart into hopper, as
bags are split out from Rubber and
static begins to charge there is a big
cloud of airborne dust settling over all
operation.
Mill operation shovels or scrapes ingredi-
ents onto through which goes Flour, From
Un Attendance, onto Floor Material Drops
From hopper to Conveyor belt which
takes upward over mill and eventually dumps
material into mill. This operation is very
dust, I imagine that fact that the material
is cold, the rollers and the electrical
heating of material causes dust to [illegible]

CRMC-ELS-Rogers-Micro-000175

Rec. A. AREA

HELPER - STANDS ON FLOOR [illegible]

[illegible]

OPERATOR - [illegible]

KILN DEDS WEIGH STATION

TWO OPERATORS WORKING THREE [illegible]


VERY DUSTY AREA - 30 TO 40 % [illegible] RESIN USED IN MIXES. DISPOSAL OF BAGS BIG PROBLEM

A" RISERS - [illegible]

AREA TO BE [illegible] AND AFTER [illegible] WALK IN [illegible] AND THE [illegible]

CONDITIONS MUST BE KEPT [illegible]

CRMC-ELS-Rogers-Micro-000176



CRMC-ELS-Rogers-Micro-000177