J.A. WOMEN - LUABON.

J.A. Barrett, London.
M.J.A. Marsh, Brussels.
W.R. Richard, St. Louis.
B.V. Weekes, Brussels.

28th January, 1971.

Monthly Report - January 1971.

Subject.

J.A. Baxter, Luabon.

Inorganic Chemicals - Fluids - W & D Marple.

Industrial Fluids.

Five technical service requests have been completed.

Technical service visits have been made to Miljeholmens in Sweden and Nokia in Finland. Tests on the first delivery of Aroclor by road tanker to Miljeholmens proved acceptable on dissipation factors. Discussion on the problem of the unwanted IR peak at 3050 cm^{-1} in Aroclor containing [illegible] 1016 showed this to be less of an issue than previously thought, but, apparently, Monsanto Aroclor shows a higher average value than Prodelec material. It had been shown from tests in the laboratory that a sample of the Aroclor delivered in the road-tanker did not show this IR peak. Some more work is planned to resolve this problem although it probably does not warrant high priority.

Askarel 1016 was presented at Miljeholmens and Nokia. Miljeholmens were not very enthusiastic, but Nokia seemed to appreciate the significance and were more interested.

Both are troubled by disposal of washing water and condenser water containing traces of Aroclor. They use water rather than organic solvents for cleaning their finished capacitors. We have been asked to help them by [illegible] plastic filter elements which they believe could remove chlorinated biphenyl from water.

Heat Transfer Fluids.

Several enquiries have been received from users of Santotherm FR-O in Finnish plants. They are concerned at toxicity effects due to leakages of Santotherm at elevated temperatures. They have been advised of correct precautions to take, including the use of cannister masks, whilst dealing with their leakage problems.

E.A.W.

J.A. Women.

DSW 378757

STLCOPCB4099963

Technical service work has been carried out for the following:

Oden Transformer Company.
Capacitor Limited.
Monsanto, Newport.
Cenemesa-Westinghouse (via Quimidroga).

We have also been asked by ICC to advise on the reason for the failure of the gasket in a transformer and we await clearance from London before doing so.

CRC.

[illegible] . CO[illegible].

DSW 378758

STLCOPCB4099964