Contains Asbestos Fibers
Avoid Creating Dust
Breathing Asbestos Dust May Cause Serious
Bodily Harm

Abex believes this warning was first placed on its asbestos-containing automotive friction products in order to comply with OSHA regulations.

Abex further states that in 1979 and 1982, it participated in the preparation and distribution of a pamphlet published by the Friction Materials Standards Institute, Inc. entitled, "Recommended Procedures for Reducing Asbestos Dust During Brake Servicing."

An excerpt of this pamphlet is reprinted below:

RECOMMENDED PROCEDURES FOR REDUCING
ASBESTOS DUST DURING BRAKE SERVICING

Because studies have indicated that exposure to excessive amounts of asbestos dust may be a potential health hazard, OSHA has set maximum limits of levels of airborne asbestos dust to which workers may be exposed. Since most automotive friction materials normally contain a sizeable amount of asbestos, it is important that people who handle brake linings and clutch facings understand the nature of the problem and know the precautions to be taken.

(1) Areas where brake work is done should be set aside if possible, and entrances should be posted with an asbestos exposure sign as follows:

Asbestos
Dust Hazard
Avoid Breathing Dust
Wear Assigned Protective Equipment
Do Not Remain in Area Unless Your Work
Requires It
Breathing Asbestos Dust May Be Hazardous
To Your Health

(2) The amount of asbestos in the dust from brake lining wear is normally at an extremely low level because of chemical breakdown during use, and if machining of friction material does not take place, simple procedures will minimize exposure. During brake servicing, the mechanic should wear a respirator approved by NIOSH for asbestos dust. It should be