(1) EXXON
(2) FILE

SMITH MARINE SERVICE, INC.

2011 BROADWAY _ P. O. BOX 12106
HOUSTON, TEXAS 77017
713/641-3451

July 17, 1978

Mr. Herb Leyendecker
Exxon Company, U.S.A.
Marine Department
P. O. Box 1512
Houston, Texas 77001

SUBJECT: Service Report; S. S. Exxon Gettysburg; Newport News, Virginia;
July 6, 1978 thru July 14, 1978:

(1) Replaced #4 Burner Auto/On Switch, Fire Room, Stb'd. Boiler.
(2) Replaced Atomizer Interlock #1 Stb'd.
(3) Replaced Open Register Interlock #2 Stb'd.
(4) Replaced Atomizer Interlock #3 Stb'd.
(5) Replaced Atomizer Interlock #4 Stb'd.
(6) Replaced Ignitor Cylinder #1 Stb'd.
(7) Replaced Ignitor Cylinder #2 Stb'd.
(8) Replaced Ignitor Cylinder #3 Stb'd.
(9) Replaced Ignitor Rod & Tip #1 Stb'd.
(10) Repaired Wiring #2 Scanner - Replaced Relay #2 Stb'd.
(11) Replaced Tubes #1 Scanner Stb'd.
(12) Replaced Scanner #2 Stb'd.
(13) Replaced APR, BR1, RR1A, TR-1 Stb'd. Boiler.
(14) Replaced Ignitor Position Switch #4 Stb'd.
(15) Replaced #1 Ignitor Cylinder Port Boiler.
(16) Repaired #4 Auto/On Swtich, Fire Room, Port.
(17) Repaired #2 Auto/On Switch Fire Room Port.
(18) Repaired #2 Auto/On Switch Engine Room Port.
(19) Replaced #3 Scanner & Relay Port .
(20) Repaired Wires #1 Atomizer Interlock Port.
(21) Repaired Wires #2 Atomizer Interlock Port.
(22) Repaired Wires #2 Scanner - Replaced Relay Port.
(23) Set All Alarms, Cut-outs, Both Boilers.
(24) Conducted U.S.C.G. Inspection.

Report By Frank L. Smith, Jr.
(SPARE PARTS & MATERIAL LIST ATTACHED)

FLS/jm
encl.