10-2-68

Hartley - DCA

Samples of fluid being sent to me

High fire switch broken - unit goes to high fire immediately

fluid so viscous that pump would not operate properly

Vibration appears to cause HF switch inconsistency.

Should check sample for contamination -

Hartley contacted Ryder

DSW 434956