12. Substitution methods

    a. Wet for dry - Wheel
    b. Do All Saw for gate burning
    c. Welding rod grinding machine for hand grinding
    d. Vacuum chip removal for shoveling

13. Welding

14. Continuity of exposure

15. Short circuit ventilation

16. General ventilation - versus local exhaust

17. Bringing material to the man

18. Cooperation with the Industrial Hygiene Department - Labor shortage

19. State labor codes