PLAINTIFF'S EXHIBIT 04866.00

U.S. DEPARTMENT OF LABOR
WAGE AND HOUR AND PUBLIC CONTRACTS DIVISIONS
Room 222, 1114 Commerce Street
Dallas, Texas 75202

ADDRESS ALL COMMUNICATIONS TO:
William J. Rogers
Regional Director

September 24, 1963

IN REPLY REFER TO:
FILE NO.
CRH:bjg

Mr. James W. McMillan, Works Manager
Pittsburgh Corning Corporation
Box 3057
Tyler, Texas

Dear Mr. McMillan:

On May 4, 1963, our investigator, Mr. H. J. Menhard, made a safety and health inspection of your operations and pointed out several conditions which do not meet the safety and health requirements of the Walsh-Healey Public Contracts Act. On September 9, 1963, our safety engineer, Mr. C. R. Holder, made a safety and health follow-up inspection of your operations and found three of the previously pointed out conditions still existing and brought nine new conditions to your attention.

I am listing below the unsatisfactory conditions.

1. Maintain material in storage in accordance with Section 50-204.62.
   a. Material stored in warehouse closer than 18 inches to the sprinkler system.

2. Maintain fire extinguishers in accordance with Section 50-204.114.
   a. Several extinguishers not properly tagged.
   b. A number of extinguishers noted with seals broken.

3. Provide adequate washing facilities in accordance with Section 50-204.244.
   a. No hot water provided in lavatories in office building.

4. Provide horn for No. 2 fork lift in accordance with Section 50-204.1(d).

5. Maintain areas where flammable liquids are stored in accordance with Section 50-204.82.
   a. No "NO SMOKING" sign posted near gasoline pump.

6. Maintain storage of flammable liquids in accordance with Section 50-204.91.
   a. Oil drums and open containers of oil noted in workroom.

7. Provide safety containers for handling flammable liquids in accordance with Section 50-204.92.
   a. Clear glass jug of gasoline noted near lawn mower in work area.
   b. Naphtha noted being handled not in safety container.

CCOBB

PLAINTIFF'S EXHIBIT WV-009781

8. Provide adequate guards for belts in accordance with Section 50-204.163.
   a. Unguarded belt drive noted on power hack saw.

9. Maintain abrasive wheels in accordance with Section 50-204.199.
   a. Tool rest not properly adjusted on bench grinder.

10. Maintain overall housekeeping in accordance with Section 50-204.229.
   a. Accumulation of dust noted on electrical fixtures and rafters.
   b. Passageways in storage room and service room not maintained in an orderly fashion.

11. Provide waste receptacles for flammable material in accordance with Section 50-204.231.
   a. Pasteboard waste containers now in use for flammable waste material.

12. Provide other personnel protective equipment for environmental conditions in accordance with Section 50-204.275.
   a. Excessive amount of asbestos dust noted near sewing operation and where ground scrap is placed in the feeders.

It is my understanding that these unsatisfactory conditions will be corrected by October 28, 1963. Please let me know on or before that date whether or not the necessary corrective action has been completed.

Sincerely yours,

William J. Rogers

William J. Rogers
Regional Director