CHG 01013

PLAINTIFF'S EXHIBIT

UPRC-144

champlin

A Subsidiary of Union Pacific Corporation

GAY

PERRYMAN

HAWKINSON

RETURN TO SAFETY & LOSS CONTROL DEPT.

INTER-OFFICE CORRESPONDENCE

TO: M. A. Hawkinson OFFICE: Ft. Worth

FROM: G. T. Westbrook DATE: October 13, 1986

SUBJECT: ARKWRIGHT-BOSTON INSURANCE RECOMMENDATIONS FOR BOILER 561-B-2

In the Loss Prevention Report dated August 13, 1986, the recommendation was made to repair the rear wall of this boiler as soon as possible.

The rear of the boiler wall refractory had begun to lean inward causing some minor deformation of the water wall tubes.

Since that report, this boiler was removed from service and the rear wall repaired by completely removing the rear wall and adding additional reinforcement. No repairs were made to the water wall tubes. Deformation was minor and did not warrant repair at this time.

G. T. Westbrook

cc: R. E. Schneck
R. W. Arey
J. H. Tansey
R. D. Madigan
Arkwright-Boston Insurance
Inspection File: 561-B-2

RECEIVED
OCT 15 1986
SAFETY & LOSS CONTROL DEPT.

CH/W-002584