Goodyear

2 primary loops

Each loop has 9 processing units for polyester. (fully interconnected).

84 MM BTU — 7 or 8 separate heaters.

Change-over estimate:

1 week on each loop

1 week continual venting of refill/settling down etc.

Has it been shut down for ~10 years so unexpected problems might arise e.g. frozen valves.

Goodyear

MKting pushing for fluid change — expansion of polyester in ~~bib bags etc~~ boil-in-bag applic^ns. Can't do this with FR.

Mfg will resist.

We would be tight on Thermind 66 to refill — need time to build inventory.

Key man to convince + work with @ Goodyear:

Jack Kreger
Sen. Supt. of Mfg.
Akron.

0048163

TOWOLDMON0055278