2.) Exposure of operator at applicator machine - borderline health hazard.

Action Taken

(a) An exhaust system as described in "Control" should be provided. A price for same has been requested from Dunner. Covered by MR #8371.

(b) Shop requisition #22024 has been issued to set large roof fan to bring air into room instead of pulling out - the latter being operator's desire.

Block Cement Compounding

3.) No comments.

4.) No comments.

NOTE: High counts as noted on page 17 should be relieved and/or eliminated as result of above action.

Hearing Conservation Survey

No comments.

Ventilation Study

This report indicates that our present system could stand some repairs and revamping. Certain cases exist where the original hood was taken off and never remodeled or replaced.

Mr. Wagner's report indicates that we should redesign our entrance fittings on the majority of our equipment. To do so will be very costly and time consuming and will not in the end solve many problems. We have to assume that the individual workman will still "doctor" or batter the ductwork as they have done in the past. Our control over this will have to be improved upon by going to disciplinary action, if necessary.

Mr. Cole was advised that after we have completed all action of the discussed items we would like him to recheck the areas concerned and again offer their comments.

Any comments you may have as to our action on any of these items will be appreciated.

W.H.Baker

W.H.Baker/pr

Safety Director.

cc: F.E.Tayler
J.Soviak
J.T. Gresh
G.A.Riley
L.E.Hamlin J.S.Holtaway