FROM H. E. ELLIS

TO MESSRS. JUERGN HERMANS
MAREOS MEDEIROS
Recife

RECEIVED
JUL 30 1981
INDUSTRIAL HYGIENE

1981 July 28

RE: ASBESTOS EXPOSURE

Because of health complications associated with asbestos exposure, the attached list contains procedures used at Badin Works that will lower employee exposure.

Contact either of us if any assistance or explanation is needed.

H. E. ELLIS
INDUSTRIAL HYGIENIST - BADIN WORKS

B. L. SICELOFF
INDUSTRIAL HYGIENIST - PITTSBURGH

HEE/BLS:bdt

Attachment

cc: E. E. Rumberger - Pittsburgh
R. W. Flanagan - Pittsburgh
J. M. Bales - Badin
R. C. Hinkle - Badin

PLAINTIFF'S
EXHIBIT
AL-829

1. Never blow off any accumulated Marinite dust since this will produce airborne fibers.

2. Use the vacuum cleaner to clean areas where sanding or drilling occurs. The vacuum cleaner should be lined with a polyethylene bag.

3. If sawing must be done, use the saw equipped with a dust collector.

4. Wear the 3M 8710 (white) respirator when any Marinite dust is produced and levels are below 20 fibers/cubic centimeter. Proper fitting and use should be maintained.

5. Contact the appropriate department when vacuum cleaner is full and disposal is necessary.

6. Dispose of dust in double bags.