MAREMONT CORPORATION

INTER-OFFICE CORRESPONDENCE

TO: W. N. Bockay

FROM: F. C. Skelton

DATE February 10, 1977

CC: D. R. Loftis
R. A. Ward

SUBJECT: DISC BRAKE INSTALLATION INSTRUCTIONS - SEARS

I have reviewed the three Disc Brake Installation Instruction sheets GB-0103, GB-0104 and GB-0105 and note one area that I think is superfluous and possibly confusing.

On GB-0104 (for Ford and some AMC vehicles) under the Caliper Assembly section for the Bendix Sliding Caliper, Item a and Illustration #14 are incorrect and unnecessary.

Similarly on GB-0105 (for AMC and Chrysler vehicles) under the Caliper Assembly section for the Kelsey-Hayes Sliding Caliper, Item a and Illustration #9 are also incorrect and unnecessary.

I think that these two sheets should be corrected. I talked to Don Loftis and understand that the initial order for GB-0104 and GB-0105 was 10,000 each. I suggest that you review this with Dick Ward and Don Loftis and decide what corrective action is required.

Frank C. Skelton

Frank C. Skelton
FCS:dp

11.3.7 R

PLAINTIFF'S EXHIBIT

MAR-229