G. L. Bratsch
G. Johnson
A. Leisy
T. W. Dalton

A. Gallion
P. E. Heisler
C. F. Buckley

ant Manager
uperintendent
upervisor

FUME REPORT

Date June 7, 1974

. Person registering complaint N/S

. Address

. Telephone number _____ Time 6/7, 6/8, 6/9/74 AM PM

. Nature of complaint: white cloud from dept 246.

. Wind direction from _____. Velocity (Strong, Mild, Calm) _____ MPH

. Conditions found on investigation:
#7 sty has hole in top of TK, blower off & supv aware of prob (HCl plus NH_3 from PNA)

7. Complaint received by _____ At _____ AM PM

8. Referred to Night Supt. at _____ AM PM Complainant called back at _____ AM PM

9. Immediate action taken by _____:

SUPERVISOR: Please reply below. Indicate Projects, Investigations, etc. and expected date of completion. After completion, mail to C. Buckley who will send a copy to your superintendent.

(1) Reduced air flow to sparger
(2) MRO to install regulator on steam to coil 76827 (6/7/74)
(3) check for steam leaks in coil
(4) MRO to repair vent, top of #7 storage 70268 (11/30/72) and 72414 (6/7/73)

10. Cause as determined by supervisor:
(5) MRO to repair cover over vent hole, top of #7 storage 76857 (6/7/74)
(6) other tank leaks around dept. contributed to fogging

Gary L Johnson

11. Corrective action by supervisor to prevent recurrence:

DSW 345390

Signature H Kellerman

STLCOPCB4084064