FORMULA SUPPLEMENT

APPROVAL:
Ind. H. A. Eschenbach H.A.E.
Hyg.
Tech. D. O'Donnell dod
Eln.
Qual. Assur. R. C. Ericson RM

PRODUCT CODE NO. 41-06-04-2-9 (Export) 41-06-04-1-19 (Domestic)

THIS DRAFT CANCELS PRIOR DRAFT NO. SA-627-1

(1) cm (2) dod (2) (4)

PRODUCT Domestic & Export Monokote 5 (715)(L3D18)

PLANT NAME Santa Ana

DRAFT NO. SA-650 -1

DATE November 12, 1981

In case of an accident or any other emergency, call CHEMTREC at 800-424-9300 for instructions on handling hazardous materials. CHEMTREC operates 24 hours per day, 7 days per week.

PACKAGING:

CONTAINER SIZE	CPD SPEC. NO.	APPROX. NET SHIPPING WT.
ve-pak bag x 29½ x 6	99-06-08-1-19	See pkg step
n-mouth bag x 38 x 8	99-16-12-1-19	



LABELLING & STENCILLING REQUIREMENTS

	SIDE	TOP
Product	☐	☐
Special Warning Label	☐	☐
Keep From Freezing	☐	☐
Stir Well	☐	☐
Address	☐	☐
Other Stencil plant I.D. on bags as outlined in formula draft	☑	☐
	☐	☐

NOTES, SAFE PRACTICE & STORAGE

aybolt Visc.

Point

Pensky-Martens C.C.

Tagliabue C.C.

Setaflash

apor Pressure @ 100°F.

landling & Storage Requirements

BILL OF LADING REQUIREMENTS

D.O.T. Class (1)

D.O.T. Article (2)

Freight Classification

Spec. B/L Marking 15193263

HAZARDOUS MATERIALS HANDLING INSTRUCTIONS

he following safety equipment is recommended for use where appropriate: respirators meeting MESA/NIOSH 21C requirements for usts and 23C requirements for vapor, gas, mist, or fumes; chemical goggles with baffles & anti-fog treatment.

HAZARDOUS MATERIALS	SAFETY PRECAUTIONS
	The following safety equipment is recommended for use where appropriate: respirators meeting MESA/NIOSH 21C requirements for dusts and 23C requirements for vapor, gas, mist or fumes, chemical goggles with baffles & anti-fog treatment.
Vermiculite	Libby: Avoid breathing dust. TLV: Airborne tremolite asbestos fiber 2f/ml. TWA 15 minute ceiling 10f/ml. Nuisance dust respirable fraction 5 mgm/m^3. Total dust 15 mgm/m^3.
	Kearney: Avoid breathing dust. Nuisance dust respirable fraction 5 mgm/m^3. Total dust 15 mgm/m^3.

1) Refer to D.O.T. Section 172.4
2) Refer to D.O.T. Section 172.5

TLV = Threshold Limit Value (A concentration, usually airborne, of a substance to which a person may be safely exposed.) It may be expressed as a Time-Weighted-Average (TWA) for an 8-hour day and a 40-hour week, or in some cases as a ceiling limit (C).

TLV = Threshold Limit Value (the amount of exposure a person may be subjected to during an 8-hour period).

FORMULA SUPPLEMENT

DRAFT NO. SA-650 -1 PRODUCT Domestic & Export Monokote 5 (715) (L3D18) BATCH NO. OR PLANT NAME Santa Ana

HAZARDOUS MATERIALS HANDLING INSTRUCTIONS

HAZARDOUS MATERIALS	SAFETY PRECAUTIONS
MKAE	May be irritating but not particularly toxic. Don't breathe dust. Use respirator. Avoid skin irritation by washing off with soap and water. No TLV set.
CELIB	Nuisance dust. TLV = 10 mg/m^3. Spontaneous combustion if brought in contact with organic material (Sawdust, Turpentine, etc.). Use respirator.
WOCH	Causes temporary skin and eye irritation and dry throat. Avoid skin contact and breathing of fiber-laden air. Use respirator & wear gloves and goggles. Avoid scratching contaminated skin. Wash with cool water. TLV is 10 mg/m^3.

15193264